

Holborn Links Estate

HLE – Project 5: 20-21 Southampton Place

SCHEDULE OF WORKS

Location	ltem	Demolitions	Proposed
Internal: Lower	1		Refurbished lift
Ground Floor	2		Existing WCs refurbished with new sanitary ware
			and finishes.
	3		Existing WC refurbished in current position
	4		All new period appropriate doors, skirtings,
			architraves and cornices throughout
	5		New floor mounted FCUs in built in joinery.
	6		Existing lobby retained.
	7	New service risers.	
	8		Courtyards refurbished with wall panelling and
			paving.
	9		New kitchenette with high and low wall mounted
			units.
	10		Wall clad in black vertical cladding.
	11		New service cupboard in existing location.
Internal: Ground	1		Existing lift refurbished.
Floor	2		Existing WCs refurbished with new sanitary ware and finishes.



	3	New condensate risers sized to allow retention of high and	
		low level historic features.	
	4	All non-historic features replaced with more in keeping	
		skirtings, architraves and cornices.	
	5		Existing windows refurbished and re decorated.
	6		Existing fireplace surrounds repaired as required and new inserts installed
	7		New capped services for future tea point.
	8	New partition formed with double doors to reinstate entrance lobby.	
	9	New door and partition installed.	
	10	Existing opening infilled to reinstated separate reception	
		room.	
	11		External store area
	12		New floor mounted FCUs within built in joinery.
Internal: Typical	1		Existing lift refurbished.
Upper Floor	2		Existing WCs refurbished with new sanitary ware and finishes.
	3	All replaced features such as skirting, architraves and cornices replaced to match existing.	
	4		New doors into offices.
	5		New floor mounted FCUs in built in joinery.
	6	New service risers sized to allow retention of high and low level historic features.	
	7		Existing fireplace surrounds repaired and new inserts installed.
	8	New openings formed in assumed modern partition.	
	9	New guarding to full height windows (first floor only).	
	10		Existing windows refurbished and redecorated.
	11	New capped services for future tea points.	



Internal: Fourth	1	New stair lobby formed.	
Floor	2	Existing assumed 1970s partitions removed, and new	
		partitions installed to rationalise room layouts.	
	3	All new doors, skirtings, architraves and cornices	
		throughout with period appropriate designs.	
	4	New caped services for future tea points.	
	5	New stair and access hatch to roof in existing access	
		location.	
	6	New opening formed in modern partition.	
	7	New floor mounted FCUs in built in joinery	
	8	New risers	
	9		Existing windows refurbished and redecorated.
	10	New casement windows.	
	11	New sash window.	
	12		Existing mansard roof upgraded with new
			insulation to improve thermal performance.

HLE – PROJECT 5: 22 SOUTHAMPTON PLACE

Location	Item	Demolitions	Proposed
Internal: Lower	А		Existing lift refurbished.
Ground Floor	В	New floor mounted FCUs in built in joinery.	
	С		Existing cupboard retained as comms room.
	D	All new period appropriate doors, skirtings, architraves and cornices throughout.	
	Е	New condensate risers	



	F		Existing courtyard cleaned and surfaces made
			good.
	G		Existing door widened and re-handed.
	Н	New kitchenette within lower ground front room in existing kitchenette location.	
	Ι		Existing window sill lowered to create new access into rear courtyard for maintenance access.
	J	New ladder installed for maintenance access.	
	K	New service cupboard in existing location.	
Internal: Ground	Α	Existing 2016 lift refurbished.	
Floor	В		New capped services for future tea point installation.
	С	WC enlarged in line with 2016 consent and refurbished with new fittings and finishes.	
	D	All non-historic features replaced with more in keeping skirtings, architraves and cornices.	
	Е		Existing windows refurbished and re decorated.
	F	Existing fireplace surrounds repaired as required and new inserts installed	
	G	Existing opening widened to create more usable access to front room	
	Н	New floor mounted FCUs within built in joinery.	
	Ι	Riser rebuilt for new services.	
Internal: Typical	Α		Existing lift refurbished.
Upper Floor	В	New guarding to full height windows (first only).	
	С	WC enlarged in line with 2016 consent and	
		refurbished with new fittings and finishes.	
	D	All replaced features such as skirting, architraves and	
		cornices replaced to match existing.	



	E	New floor mounted FCUs in built in joinery.	
	F	New service riser.	
	G	Existing fireplace surrounds repaired and new inserts installed.	
	Н	New capped services for tea points.	
	Ι		Existing office doors retained.
	J		Existing windows refurbished and redecorated
Internal: Fourth	Α		Existing lift overrun.
Floor	В	Existing assumed 1970s partitions removed, and new	
		partitions installed to rationalise room layouts.	
	С	All new doors, skirtings, architraves and cornices throughout	
		with period appropriate designs.	
	D	New cleaners cupboard within existing plant room.	
	Е	New stair and access hatch to roof within existing plant room	
		to open up rear room - stair to match rise and going of existing	
	F	New landing formed.	
	G	New floor mounted FCUs in built in joinery.	
	Н	New service riser.	
	Ι	New capped services for tea point.	
	J		Existing windows refurbished and redecorated.
	K	New sash window	

HLE – PROJECT 5: 20-22 SOUTHAMPTON PLACE (INCLUSIVE)

Location	Item	Demolitions	Proposed
	1		Existing roof overlain with new roofing membrane.



External: Roof	2	Existing plant removed and new plant			
Plan		consolidate to the back of the roof.			
	3	Existing guarding removed and new guarding			
		installed to improve roof access			
	4	New access hatch from relocated stairs below.			
	5		Existing roof overlain with new roofing insulation and membrane		
			to improve thermal performance of building.		
	6	New access hatch from stairs below.			

HLE – PROJECT 5: 46-47 BLOOMSBURY SQUARE

Location	Item	Demolitions	Proposed
Internal: Lower	1		Existing lift refurbished.
Ground Floor	2		Existing WC refurbished with new sanitary
			ware and finishes.
	3		Existing vaults unaltered.
	4	All new doors, skirtings, architraves and cornices throughout.	
	5	New M&E installed to courtyard recess	
	6		Courtyards refurbished with new decking
	7	New comms cupboard.	
	8		New M&E cupboard in old location.
	9		Existing pavement vault utilised for plant.
	10	New floor mounted FCUs in built in joinery	
	11	New risers.	
	12	New external stairs.	



	13	Form new opening within passageway.	
Internal: Ground	1		Existing lift refurbished.
Floor	2		Existing WC refurbished with new sanitary
			ware and finishes.
	3	Form new double door opening in existing wall.	
	4	New stair to lower ground for bike access.	
	5		Existing fireplace surrounds repaired and
			new inserts installed.
	6		Existing fire escape arrangement retained.
	7	New floor mounted FCUs in built in joinery.	
	8	New risers sized to allow retention of high and low level historic	
		features.	
	9	All replaced features such as skirtings, architraves and cornices	
		replaced to match existing.	
	10	New doors to offices.	
	11		Existing windows refurbished and
			redecorated.
	12	New capped service provision for future tea points.	
	13	New casement window.	
Internal: Typical	1		Existing lift refurbished.
Upper Floors	2		Existing WC refurbished with new sanitary
			ware and finishes.
	3	Form new opening in existing wall within previous opening	
		location.	
	4	All replaced features such as skirtings, architraves and cornices	
		replaced to match existing.	
	5	Existing fireplace surrounds repaired and new inserts installed.	
	6	New panelled office doors.	
	7	New floor mounted FCUs in built in joinery.	



	8	New service risers sized to allow retention of high and low level historic features.	
	9	New guarding to full height windows (first floor only).	
	10	New free standing tea points within joinery.	
	11		Existing windows refurbished.
	12	New casement window.	
Internal: Fourth Floor	1	New stair lobby formed.	
	2	Existing assumed 1970s partitions removed to rationalise room	
		layouts.	
	3	All new doors, skirtings, architraves and cornices throughout	
		with period appropriate designs.	
	4	New capped service provision for future tea point.	
	5	New roof access in existing location.	
	6		Existing windows refurbished and
			redecorated.
	7	New floor mounted FCUs in built in joinery	
	8	New service risers.	
External: Roof Plan	1		Existing roof overlain with new roofing
			membrane.
	2	Existing plant removed and new plant consolidate to the back	
		of the roof.	
	3	Existing guarding removed and new guarding installed to	
		improve roof access.	
	4	New access hatch stairs below.	



ELEVATIONAL ENHANCEMENTS / RESTORATION WORKS: 20-22 SOUTHAMPTON PLACE

Location	Item [PAYE Survey Reference]	Demolitions	Proposed
Front Elevation	1 [SP20-21.01-02]		
	2 [SP20-21.03-04]		
	3 [SP20-21.05-06]		
	4 [SP20-21.07-08]		
	5 [SP20-21.09]		
	6 [SP20-21.10-12]		
	7 [SP20-21.13-15]		
	8 [SP20-21.16-17]		
	9 [SP22.01-02]		
	10 [SP22.03,05]		
	11 [SP22.04]		
	12 [SP22.06]		
	13 [SP22.07]		
	14 [SP22.08]		
	15 [SP22.09]		
	16 [SP22.10-12]		
	17 [SP23.01]		
	18 [SP23.02]		
	19 [SP23.03]		
	20 [SP23.04]		
	21 [SP23.05]		
Rear Elevation	22 [SPR20-21.18]		
	23 [SPR20-21.19]		
	24 [SPR20-21.20,23]		
	25 [SPR20-21.21-22,24-27]		



ELEVATIONAL ENHANCEMENTS / RESTORATION WORKS: 46-47 BLOOMSBURY SQUARE

Location	Item [PAYE Survey Reference]	Demolitions	Proposed
Elevation 08-02 / Elevation 07-01	26 [BS46/47.01]		
	27 [BS46/47.02-03]		
	28 [BS46/47.04-05]		
	29 [BS46/47.06-08]		
	30 [BS46/47.09-09a]		
	31 [BS46/47.10-11]		
	32 [BS46/47.12-13]		
	33 [BS46/47.14-15]		
	34 [BS46/47.16]		
	35 [BS46/47.17-18]		
	36 [BS46/47.19-22]		
	37 [BS46/47.23-26]		
	38 [BS46/47.27]		
	39 [BS46/47.28-30]		