

Typical Joinery Alteration (5th Floor East) - Internal Elevation

1:10