
## insecure timber trellis to perimeter of outrigger removed Roof tiles to be— removed and re-laid to correct falls Non-original built-in joinery removed У в Contemporary cork bathroom stripped out and reconfigured Non-original door and wall removed Non-original stair and cupboards removed Non-original built-in—— joinery removed

 $\triangleright$ 

Existing unsafe and—



P4	28.07.2022 Issued for Plann		ng	KS	HJ
РЗ	26.07.2022	Draft Planning Is	sue	KS	HJ
P2	13.07.2022	Draft Planning Issue		KS	HJ
P1	01.06.2022	Draft Planning Is	sue	KS	HJ
rev	date	description		revised by	audited by
stage PLANNING Second			oor Plan		suitability code <b>S2</b>
	PLA	TON NT CHITECTS	CONTRACTORS ARE NOT TO SCAL University House 53-55 East Road London N1 6AH client Matthew & Sharon Donaldson	E	T +44 (0)20 7288 1333 F +44 (0)20 7288 0333 mail@lparchitects.co.uk ' www.lparchitects.co.uk
	∖\ THIS D	RAWING IS COPYRIGH	т		
<sup>scale</sup> 1:50@A1 1:100@A			iginator zone level ty LPA - ZZ - xx - D	pe role dwg R - A - 3.0	





Demolition