

PROPOSED LEGEND

- 1. External fabric cleaned and made good where retained
- 2. All existing windows to be surveyed and refurbished by specialist subcontractor
- 3. New glazed terrace door system
- 4. Existing roof-lights refurbished
- New timber shop-front with double main entrance doors
- 6. New timber shop-front with fire escape door (to match main
- 7. New timber framed window at ground floor to match form of existing windows
- 8. LGF- GF escape stair retained, refurbished and decorated
- 9. New cycle rail to LGF access stair
- 10. External light-well finishes made good and decorated
- 11. New timber decking to terraces
- 12. Existing balustrade refurbished (scope tbc)
- 13. New PPC metal balustrade
- 14. New metal and timber balustrade
- 15. New external lighting
- 16. New dormer windows subject to e by specialist
- 17. New terrace door opening and timber framed door with glazing panel
- 18. New access control panel / signage main entrance
- 19. Roof plant screen retained with new plant behind

