



Photo 1: Original buried bottom step to existing stair, with non-original brick back fill





Photo 2: Original historic buried gully in comparison with non-original gully showing difference in level, with non-original back fill surrounding





X

Photo 3: Non-original back fill removed, exposing full length of original historic stair and original concrete slab





Photo 4: Close up photo highlighting the following:

- Original newel post relocated
- Rounded end spliced onto existing square tread at bottom of non-original stair location
- Fixing points for historic balustrade on each buried historic tread
- Buried historic treads are worn down in centre showing relatively recent infill
- Original historic bottom step showing rounded end
- Existing gully under board





Photo 5: Original historic air brick located at bottom of the historic stair, showing that the original lightwell level was significantly lower than the existing