

9 Lyndhurst Terrace
RIBA Stage 4

Amendment No.	Description	Position	Reason
A/01	Ground and First Floor arch composition exchanged	East Elevation, Ground & First Floor	Lift dimensions changed since planning, opening from Vestibule is too small
A/02	Brick Intersection	East, West and South Elevation	Detailed development
A/03	Glazing beads	East, West and South Elevation	Full height windows proved too costly and impractical
A/04	Omitment of windows	South Elevation	Cost saving

