



EXISTING COAL VAULT IS DAMAGED FROM WATER INGRESS


1 Existing - Basement Floor Plan



EXISTING PINE DOOR IS DAMAGED FROM LACK OF MAINTENANCE AND PROLONGED EXPOSURE TO DAMP




2 Existing - Basement Elevation



THE CHIMNEYS HAVE BEEN DECOMMISSIONED, THE FLUES REMOVED AND THE BREAST IS CAPPED (NON ORIGINAL INTERVENTION)

3 Existing - Section AA'

Project No	Project	Address		Title		Scale		RIBA CHARTERED PRACTICE T: +44(0)7438 46 23 51 M: alex@iungostudio.com W: www.iungostudio.com	figured dimensions only to be taken from this drawing. All dimensions are to be checked on site before any work is put in hand If in doubt, ask.
075	Medburn St	31 Medburn St, London NW1 1RH		Existing Basement/Section					
Revision	Client	Author	Checked	Drawing No		Date			
	Ms Alina Gerasimenko & Mr Caspar Bartscherer	AC	OB	075(P)031		28/07/2022			