

Application No:	Consultees Name:	Received:	Comment:	Response:
2022/3230/L	M green	10/10/2022 11:52:15	COMMNT	Hcaac is disappointed that the intricacy of door main frame shown in existing photographs were not replicated . HCAAC would recommend that any reproductions of heritage assets / windows doors should include the whole asset. For example if the shop window to be replicated in this instance the stall riser and frame to be part of renewal, with all details surveyed and materials and profiles to match existing asset.
2022/3230/L	M green	10/10/2022 11:53:47	COMMNT	Hcaac is disappointed that the intricacy of door main frame shown in existing photographs were not replicated . HCAAC would recommend that any reproductions of heritage assets / windows doors should include the whole asset. For example if the shop window to be replicated in this instance the stall riser and frame to be part of renewal, with all details surveyed and materials and profiles to match existing asset.