


THIRD FLOOR PLAN

AS EXISTING





Existing lead dormer in poor condition Existing poor quality roof lights Existing lead section in poor condition