

Application No:	Consultees Name:	Received:	Comment:	Response:
2022/5378/T	Steve G	28/12/2022 11:04:20	OBJ	The crown of this tree has been very recently and drastically reduced by several meters, which is a proven method to slow down and prevent any further damage to the surrounding buildings. As a result, a few years of maintenance (including reducing the crown every 3-4 years) and monitoring should be enforced before any further action is taken. Following the recent crown reduction, any damage to the property should be properly documented (photos and dimensions of any cracks to be submitted as evidence) before the Council can consider approving to fell such an important tree in the neighborhood - this action would affect everyone in the neighbourhood, so please consider alternative methods such as the recent crown reduction of a few months ago before felling. Thank you.
2022/5378/T	Steve G	28/12/2022 11:02:40	OBJ	The crown of this tree has been very recently and drastically reduced by several meters, which is a proven method to slow down and prevent any further damage to the surrounding buildings. As a result, a few years of maintenance (including reducing the crown every 3-4 years) and monitoring should be enforced before any further action is taken. Following the recent crown reduction, any damage to the property should be properly documented (photos and dimensions of any cracks to be submitted as evidence) before the Council can consider approving to fell such an important tree in the neighborhood - this action would affect everyone in the neighbourhood, so please consider alternative methods such as the recent crown reduction of a few months ago before felling. Thank you.

Total: 4