


ARBORICULTURAL ASSESSMENT REPORT

For:	Client:	Sedgwick International UK
	Insurer:	[REDACTED]
Site:	Policyholder:	[REDACTED]
	Risk Address:	45 Gondar Gardens, London, NW6 1EP
Refs:	PRI Ref:	[REDACTED]
	Client Ref:	
	Insurer Ref:	

Arborist Name:	Will Hinde	Date:	23/10/2020
QC:	Thomas Peppiatt	Date:	27/10/2020



CONTENTS

1.0 INTRODUCTION & BRIEF	3
2.0 LIMITATIONS.....	3
3.0 DISCUSSION AND ANALYSIS	4
4.0 CONCLUSIONS AND RECOMMENDATIONS.....	5
5.0 STATUTORY CONTROLS.....	5
6.0 APPENDIX 1: TREE TABLES	6
7.0 APPENDIX 2: SITE PLAN.....	10
8.0 APPENDIX 3: SITE PHOTOGRAPHS.....	12



1.0 INTRODUCTION & BRIEF

- 1.1** Property Risk Inspection has been instructed behalf of the building insurers of the insured property. We have been advised that the insured property has suffered differential movement and damage that is considered to have been caused by trees growing adjacent to the property influencing soils beneath its foundations.
- 1.2** We have been instructed to undertake a survey of the vegetation growing adjacent to the insured property in order to provide our opinion as to whether, based on the available information, any of this vegetation is likely to be influencing soil moisture levels beneath the foundations of the property, and if so, to provide recommendations as to what tree management could be implemented to effectively prevent damage continuing.
- 1.3** The vegetation growing adjacent to the risk address has been surveyed from the ground. All distances are measured to the nearest point of the risk address unless otherwise stated.

2.0 LIMITATIONS

- 2.1** Recommendations with respect to tree management are associated with the risk address as stated on the front cover of this report and following consultation with investigating engineers. The survey of trees and any other vegetation is associated with impacts on the risk address subject of this report. Matters of tree health, structural condition, and/or the safety of vegetation under third party control are specifically excluded. Third party land owners are strongly advised to seek their own professional advice as it relates to the health and stability of trees under their control.
- 2.2** Recommendations do not take account of any necessary permission (statutory or otherwise) that must be obtained before proceeding with any tree works.
- 2.3** Recommendations do not take account of any requirements for survey or mitigation relating to European or other protected species, e.g. bird nesting or bats. Land owners must obtain their own professional advice in respect of any protected species.



3.0 DISCUSSION AND ANALYSIS

3.1 Soils, soil water and vegetation

All vegetation requires water to live, and this water is substantially accessed from the soil within which the plants' roots grow.

If the soil is classified as a clay soil, then it will hold very much more water than sands, gravels and loam soils. As plants abstract water from the clay soil, the soil volume will 'shrink' and 'swell' during the summer as water is first removed and then added by summer rainfall. In years in which rainfall during the summer is less than the total amount of water taken from the soil by plants, shrinkage will occur. This shrinkage may remove support from building foundations, leading to cracking in the fabric of the building.

3.2 Vegetation management

The control of trees, shrubs, and climbers, by removal or pruning as appropriate, are proven techniques that can control total soil water loss thereby minimising soil shrinkage and allowing repairs to proceed.

If vegetation management works are carried out promptly, then repairs can usually proceed very quickly and the duration and distress associated with the disruption that tree related subsidence brings can be minimised.

3.3 Third party liaison and statutory controls

Tree roots do not respect physical or property boundaries and can travel for many metres beyond the above ground 'dripline' of the canopy of the vegetation.

The purpose of this report is to ascertain which vegetation is the most likely substantial and/or effective contributory cause of the damage witnessed to allow for liaison with third parties or with local administrative Councils as necessary.

3.4 Evidential framework

The engineer has determined on a preliminary basis the damage to the property, its location and the likely mechanism of movement, and has concluded that the building failure is related to differential subsidence damage caused as a result of the action of vegetation.

Where a factual geotechnical report has been completed, this will describe the below ground foundation design, soil and geotechnical conditions, as well as any root identification where available.



4.0 CONCLUSIONS AND RECOMMENDATIONS

4.1 Recommendations

On the basis of our findings, we have considered a practical vegetation management specification.

This specification will assist in reducing the impact of the adjacent vegetation on soil moisture levels, thereby potentially stabilising foundations of the affected area of the building.

Where felling has been proposed, this will be on the basis that the vegetation in question would not respond well to a severe reduction in leaf area that would inevitably lead to decay, the development of potential hazards, and an annual or other on-going management commitment and cost.

If pruning is recommended, the specification will be designed to allow continual ease of re-pruning with a reasonable prospect of a reduction in soil water use.

4.2 Recommended vegetation management to address the current subsidence:

Tree No:	Species	Works Required
T4	Oak	Fell and treat stump (deciduous)

5.0 STATUTORY CONTROLS

London Borough of Camden Council has confirmed that none of the implicated vegetation is subject to a Tree Preservation Order or Conservation Area controls.

6.0 APPENDIX 1: TREE TABLES



Tree No	Common Name	Age Class	Condition	Height (m)	Crown Spread (m)	Stem diam. (mm)	Dist to bldg. (m)	Roots Implicated	Pruning history	Recommendation	Tree work constraints	Notes	Owner address	Owner
C1	Jasmine	Early Mature	Good	6	2	5	0.5	N	Subject to past management.	No work required.			Boundary vegetation	UKN
S1	Rose	Semi-Mature	Good	1.5	1.0	10	2.9	N	Subject to past management.	No work required.			45 Gondar Gardens London NW6 1EP	PH
SG1	Mixed species shrubs	Early Mature	Good	3	2	25	4	N	Subject to past management.	No work required.		Includes Hydrangea, Rose, Jasmine, Choisya, Magnolia and Pyracantha.	45 Gondar Gardens London NW6 1EP	PH
SG2	Mixed species shrubs	Semi-Mature	Good	2	1.0	10	4.4	N	Subject to past management.	No work required.		Includes Jasmine, Camelia, Rose and Honeysuckle.	45 Gondar Gardens London NW6 1EP	PH
T1	Elder	Early Mature	Good	3.5	2	60*	4.5	N	Subject to past management.	No work required.			47 Gondar Gardens London NW6 1EP	P3P

Tree No	Common Name	Age Class	Condition	Height (m)	Crown Spread (m)	Stem diam. (mm)	Dist to bldg. (m)	Roots implicated	Pruning history	Recommendation	Tree work constraints	Notes	Owner address	Owner
T2	Apple (Crab)	Mature	Good	5	4	120	12	N	Subject to past management.	No work required.			47 Gondar Gardens London NW6 1EP	P3P
T3	Lime	Mature	Good	17	8	500*	20	N	Subject to past management.	No work required.		Location estimated, unable to see fencelines.	39 Gondar Gardens London NW6 1EP	P3P
T4	Oak	Mature	Good	21.2	12	950	24	Y	Subject to past management.	Fell and treat stump (deciduous).	Access through building.	Located on fence line, looks likely to be PH owned. Cavity in base.	Boundary Tree	UKN
T5	Oak	Mature	Good	18	12	1000*	33	N	Subject to past management.	No work required.			District Land Registry Search Required	UKN
T6	Ash	Mature	Good	19	8	400*	28	N	Subject to past management.	No work required.			49 Gondar Gardens London NW6 1EP	P3P
T7	Poplar (Lombardy)	Mature	Good	22	8	800*	30.0*	N	Subject to past management.	No work required.			49 Gondar Gardens London NW6 1EP	P3P



Tree No	Common Name	Age Class	Condition	Height (m)	Crown Spread (m)	Stem diam. (mm)	Dist to bldg. (m)	Roots Implicated	Pruning history	Recommendation	Tree work constraints	Notes	Owner address	Owner
T8	Ash	Early Mature	Fair	1.5	1.0	50*	1.7	N	Subject to past management.	No work required.		Has been cut down to height of Jasmine.	47 Gondar Gardens London NW6 1EP	P3P

* Value is estimated



7.0 APPENDIX 2: SITE PLAN










Location:	45 Gondar Gardens, London, NW6 1EP
Job Ref:	[REDACTED]
Survey Date:	23/10/2020 - NTS
By Property Risk Inspection - Insurance Services	
Crown copyright 2016. License number 100043594	






8.0 APPENDIX 3: SITE PHOTOGRAPHS



	
SG1 - Mixed species shrubs	SG1 - Mixed species shrubs
	
SG2 - Mixed species shrubs	T1 - Elder
	
T2 - Apple (Crab)	T3 - Lime
	
T3 - Lime	T4 - Oak
	
T4 - Oak	T4 - Oak



	
T4 - Oak	T5 - Oak
	
T5 - Oak	T6 - Ash
	
T6 - Ash	T7 - Poplar (Lombardy)
	
T7 - Poplar (Lombardy)	C1 - Jasmine
	
S1 - Rose	T8 - Ash



Property Risk Inspection

