


Survey Details & Structural Defect Report

Customer Contract No. 30361315	Surveyor: AGardner	Survey Date: 2/9/22
Remove box sash + bolster wall removal.  Timbers 4x2 3x2.5m.		

Customer's Name (print): _____ Signature: _____ Date: / /

INTERNAL COSTING SHEET

ADDITIONAL PVC-U TRIMS	COLOUR	CHARGED	LENGTH	QTY
20mm x 4mm Batten				
28mm x 6mm Batten	White		4.5	3.
19mm x 12mm Rectangle				
19mm Quadrant/12mm Quadrant				
45mm x 6mm Architrave				
60mm x 6mm Architrave	White		4.5	2.
90mm x 6mm Architrave				
185mm Window Board				
200mm Window Board				
240mm Window Board AT Gable	White		1.5m	1
405mm Window Board			+ 2 end caps	
300mm x 9mm Capping Board				
Reveal Liner 100mm /210mm	White		4.5	2.

BUILDING WORK SUMMARY	LENGTH	WIDTH	HEIGHT	QTY
Bay Sundry Surcharge per Side - Not 1st side				1
Box Sash removal and make good				
3 Segment Sash Box Bay removal and make good				
Bolster Wall removal and make good x	1.1	1.1		1
Tile Sill removal				
Curved Infill - white/foiled				
Plant on Bay window < 2.5m or Plant on Bay window > 2.5m				
Lintel and brickwork removal				
Forming new brickwork (m ²)				
Porch Base				
Roof Type - felt/pitched/hipped				
Hardwood W/Board				