
8810 mm

E - 01 4110 mm

<u>E - 00a</u> 0 mm

<u>E - B1</u> -3190 mm

E - 00













W.03.05

NOTES:

interest.

W.02.07 NOTES: Weighted sash 6 panel sashes

OK condition

pre-existing).

Modern casement Post condition

Modern casement window. Lowest significance. No other related detail of

No related detail of interest. Non original dormer (widened

Manually operated blinds shut

Original 6x6 casement sash window. Highest significance. Simple detailing to panelled

shutters and panel beneath window reflecting hierarchy of the original house. Shutters fixed shut and overpainted with signs of repair and filling. Reasonable condition. Highest

W.01.07

NOTES:

Weighted sash 6 over 9 panel sashes Shutters historic and probably original Painted sash Manually operated blinds Pipework through panel

Chamfered reveals and shutters. Shutters appear to be replacements. Shutters fixed shut and overpainted with signs of repair and filling. Reasonable condition. Medium to high significance. Windows have no horns and appear to be original to thebuilding although the glazing is later and sources record that the windows of the first floor were blown out (including glazing bars) during WWII. In addition, it has been reported that the windows to no. 34 were replaced in the 1920s to match those at no. 35 (the windows to no. 34 having been replaced in the 19th century). Given the importance of the first floor windows and appropriate detailing these are considered to be of









NOTES:

Weighted sash 6 panel sashes Pipework through panel Electric operated blinds

the highest signficance.

Chamfered reveals and shutters original with evidence of past repair. Reasonable condition but fixed shut and painted over. No panel beneath window (behind modern radiator). Panelling similar to second floor window above but with reduced proportions reflecting the importance of the first floor in the building hierarchy. Highest significance. Windows have horns and glazing bars that lack the finesse of original windows suggesting post late Victorian date. Glazing bar pattern matches the 1919 front door suggesting all of the windows at ground floor were altered to match.

W.B1.04

NOTES:

Historic window possibly 20th century but without horns. Very modest detailing. Medium significance.



- - - - Electrical wiring

1:25 / 1:50 **Existing Internal Elevations**

E3003 - Existing Internal Elevations Window Stack 03

BW125 - BW - ## - XX - DR - E3003

Window Stack 03

BUILT.WORKS

BW125 AA Minor Works

Architectural Association

020 86385945 info@built.works @built.works www.built.works

3-5 Bleeding Heart Yard, London, EC1N 8SJ