E - 03 _____

E - 02 8810 mm

E - 01 4110 mm

<u>E</u> - <u>00</u>a_



















W.03.03

NOTES:

Modern casement Post condition

Modern casement window. Lowest significance. No related detail of historic interest. No related detail of interest. Non original dormer (widened pre-existing).

W.02.04

NOTES:

Weighted sash 6 panel sashes OK condition

1920s window without horns. Shutter boxes fixes with panelling below. Possibly later shutters, 1920s also? Medium to high significance.

W.01.04

NOTES:

Weighted sash 6 over 9 panel sashes Painted shutters Manually operated blinds Pipework through the panel

Fixed shut and painted over shutter boxes in squared reveals and distinct from those to no. 34. Poor condition but appear to have been opened previously. Highest significance. Windows have no horns and appear to be historically detailed although the glazing is later and sources record that the windows of the first floor were blown out (including glazing bars) during WWII. Given the importance of the first floor windows and appropriate detailing these are considered to be of the highest signficance.

W.00.03

NOTES:

Weighted sash 6 panel sashes OK condition Pipework through panelling Electric operated blinds

Square reveals to former no. 35 with shutters painted shut. Reasonable condition. Highest significance. Windows have horns and glazing bars that lack the finesse of original windows suggesting post late Victorian date. Glazing bar pattern matches the 1919 front door suggesting all of the windows at ground floor were altered to match.

W.B1.03

NOTES:

New radiator

Historic window possibly 20th century but without horns. Very modest detailing. Medium significance.

BUILT.WORKS 020 86385945 info@built.works @built.works www.built.works

3-5 Bleeding Heart Yard, London, EC1N 8SJ

BW125 AA Minor Works

Architectural Association

KEY PLAN

---- Electrical wiring

1:25 / 1:50

Existing Internal Elevations Window Stack 06

BW125 - BW - ## - XX - DR - E3006