

W.03.11

NOTES :

Modern casement
 Post condition
 Studwall cuts across

1920s sash with horns. Historic
 modest panel behind radiator
 reflecting floor hierarchy.
 Medium to high significance.



W.02.14

NOTES :

Weighted sash
 6 panel sashes
 Shutter box non functioning
 OK condition

1920s sash windows with horns
 in former stairwell to no. 35.
 Linings to window but no
 shutter boxes.



W.01.13

NOTES :

Weighted sash
 6 over 9 panel sashes
 Painted shutters
 Manually operated blinds shut
 Pipework through panels

Former location of principal stair to no. 35
 Bedford Square. Historic plans indicate
 that the windows to the rear elevation
 were reconfigured and made narrower
 when the staircase was removed. The
 window are surround therefore relate to
 works undertaken in the early 20th
 century and are tied to the removal of the
 staircase and the reworking of levels.



W.00.10

NOTES :


Modern window of lowest
 significance.




D.B1.38 W.B1.09

NOTES :

Window / door not visible from section cut



36 35 34



Rev	Date	Description	Author	Checker

Scale at A1 / A3

1:25 / 1:50



Drawing Name

Existing Internal Elevations
 Window Stack 14

Drawing Number Revision

BW125 - BW - ## - XX - DR - E3014