existing georgian wire glazed lanterns are in a poor state of repair and allowing water ingress into the existing building. Surrounding asphalt flat roofs are in a poor state of repair also.

Existing lanterns to be removed.

existing georgian wire glazed lanterns are in a poor state of repair and allowing water ingress into the existing building. Surrounding asphalt flat roofs are in a poor state of repair also.

N

0 1 2 3 4 5 6 7 8 9 10

SCALE: meters

Revision	Date	Amendment	Notes
P1.	02.01.2019	Planning Issue	

NO DIMENSIONS ARE TO BE SCALED FROM THIS DRAWING. THE CONTRACTOR/MANUFACTURER IS RESPONSIBLE FOR CHECKING ALL DIMENSIONS AND QUERYING ANY DISCREPANCIES. THIS DRAWING IS THE PROPERTY OF BDA ARCHITECTS LTD. COPYRIGHT IS RESERVED BY THEM AND THE DRAWING IS ISSUED ON CONDITION THAT IT IS NOT COPIED, REPRODUCED, RETAINED OR DISCLOSED TO ANY UNAUTHORISED PERSON, EITHER WHOLLY OR IN PART, WITHOUT WRITTEN CONSENT.

Client University College London
Project Wilkins Building Core Areas - The Old Refectory
Drawing First Floor Plan - As Existing

Scale 1:50 @ A1
Date December 2018
Drawn CL

Project N° **791**
Drawing N° **791/PL/203**
Revision P1

Burwell Deakins

info@burwellarchitects.com
www.burwellarchitects.com

Unit 0.01
California Building
London SE13 7SF
+44 (0) 2083 056010

First Floor
6 Southernhay
West Exeter EX1 1JG
+44 (0) 1392 423981