Steel framed windows to be replaced WG.05, WG.07, W1.04.
UPVC window to be replaced W1.03
Original typical timber window W1.06

Towards walkway

Existing Side Elevation facing Southeast

Towards garden

W1.04

WG.07

W1.06

WG.05

W1.03

WG.06

Existing Rear Area Elevation facing southwest adjacent to walkway

1 The Contractor must check and confirm all dimensions

2 All discrepancies must be reported and resolved by the architect before works commence

3 This drawing is not to be scaled

4 All work and materials to be in accordance with current applicable Statutory Legislation, Codes of Practice, British Standards and EU Regulations

5 Drawings show design intent only. It is the Contractor's responsibility to ensure that the construction is sound and fit for use, in accordance with the Client's requirements.

Revisions.