The Copyright of this drawing remains with The Fulker Consultancy Ltd and is not to be reproduced without written approval.



FRONT ELEVATION

Proposed Window and Door Repair

1:100

Legend

- Carefully remove defective cills and replace to match existing to clause C51/370 to match fully with existing, housed to frame the individual sash and casement and leave ready for decoration. Make good internally and externally to match existing.
- Overhaul windows, replace putties as clause L40/210, undertake scarf and inset repairs to frames, sashes and linings. Localised replacement of sash frames as clause L10/250.
- Carry out draughtproofing to window units. See separate drawing 200-21. 'Repair Care International System' to all open joints and repairs.
- Carefully remove defective doorset and replace to match existing to clause L20/270 and leave ready for decoration. New door to be hung on 1 ½ pairs of hinges to Clause L20/850. Remainder of ironmongery to be existing and re-used.
- Replace glazing to clause L40/210

REAR ELEVATION

Proposed Window and Door Repair

1:100

1:100 0 2m 4m 6m 8m 10m

rev.	description	date	chkd.
C	Specification notes revised.	09/03/20	
B	Scope of works to windows revised.	Feb 20	
A	Scope of works to roof and clerestory windows revised.	Feb 20	

client : UCL

project : The Slade School of Fine Art
Gower St, London, WC1E 8BT
External Refurbishment

drawing title : Front and Rear Elevations
Proposed Window and Door Repairs

FulkersBaileyRussell
london I gravesend I brighton | bristol I leeds I reading I manchester
info@fulkers.co.uk // www.fulkers.co.uk // 01474 369175

drawn: SL	chkd :	date: Jan 2020
status: Planning		scale: 1:100 @ A1
proj no : 19-2306		
drg no : 200-04		rev no: C