Original dividing (party) wall to adjoining house - existing Roman cement in-situ run cornice over terracotta creasing tiles evidence original coping provision to wall

Reinstatement of the saltire detail between London stock brick piers - bond identical to original examples adjacent to the house, verified with archive photographs

Removal of existing modern cement mouldings and soldier course coping.

note existing fragment of Roman cement band set below saltire blocks and evidence of stepped fracture between original gate post (No.22) and rebuilt gatepost/wall to no.23. The band aligns with the proposed reinstatement on No.23.

existing beech hedge

adjoining property

22

5.0m

1.0m

scale 1:50

N

Existing vertical fracture adjacent to Lime tree/sign location requiring new brickwork stitched in using lime-based mortar and pointing - note potential requirement for bridging lintel across tree roots if discovered to be pressurising wall - use of visible concrete lintel to be avoided

Existing frost damaged soldier course with cement mortar - removal to reinstate level wall for fitting of saltire blocks

detail of adjoining property original open saltire blocking (under Ivy) at same height level as the proposed reinstatement at number 23

revisions
A 07.06.2022 removal of soldier course coping

copyright is retained ©

arts lettres techniques ARCHITECT Arts Lettres Techniques Limited 2022

33A ARLINGTON ROAD LONDON NW1 7ES T: (020) 7383 4778 architect@artslettres.com

ALL DIMENSIONS MUST BE VERIFIED ON SITE

PROJECT 23 Gloucester crescent NUMBER GC 503 SCALE 1:50 @ A3

SUBJECT West elevation existing REVISION DATE 01/05/22