



Loft
Mineral wall insulation between ceiling joists

Access to loft
Access hatch to rear slope with water ingress around access hatch into either side assume that's what led to failure of ceiling below roof covering seems to be too hard to determine Seems to be a brittle paperlike material below the actual roof covering ceiling joists are generally boarded flat roof section timber boarded assume lead on top

Planning & LBC




BB PARTNERSHIP
 CHARTERED ARCHITECTS
 Studios 33-34, 10 Hornsey St, London. N7 8EL
 Tel 020 7336 8555 - e-mail - architect@bbpartnership.co.uk

Project
 25 Chester Terrace
 London, NW1 4ND
Drawing
 Existing
 Roof Plan

Rev	Notes	Date	By

Date	Scale	Drawn
Oct 22	1:50@A3	CS
drwg. no		Rev.
GHV-105		-