

F	CONSENT OF BOWKER SADLER PARTNERSHIP LIMITED WHICH RESERVES ALL ITS RIGHTS
	30WKER SADLER PARTNERSHIP LIMITED ASSERTS ITS RIGHTS 3E IDENTIFIED AS THE AUTHOR OF THIS DESIGN
	REPORT ERRORS & OMISSIONS TO ARCHITECT. CHECK ALL DIMENSIONS ON SITE DRAWING TO BE READ IN CONJUNCTION WITH THE HEALTH ANI SAFETY PLAN AND ALL RELEVANT RISK ASSESSMENTS
Survey drawings are kindly provided by Malcom Hughes Land Surveys Ltd and are assist to accurately describe the existing buildings, services and external spaces. KEY Features windows	
bhc	bottom hung timber casement window
thc	top hung timber casement window
shc	side hung casement
vss	vertical sliding sash timber window
tt	tilt and turn window
fl	fixed light timber window
frl	roof light (flat roof)
vrl	velux style roof light (pitched roof)
crl	conservation style roof light (pitched roof)
h	ceiling hatch
sd	sliding door
pd	pivot door
ventila	tion and flues
f	wall / roof mounted flue to gas boiler / gas fire, terminal colour is black
ab1	air brick wall terminal as extract to bathrooms, kitchens etc, annexe only. standard WL38 weather louvre, various sizes, ir powder coated aluminium, colour to suit brickwork
ab2	air brick wall terminal as extract to bathrooms, kitchens etc, main house and lodge. 225x225mm bespoke hit and miss w with vertical slots in powder coated aluminium, colour is black
ab3	as ab2, with flyscreen removed for greater ventilation rate
ab4	re-use existing terracotta airbrick
vt	low profile ventilated roof tile, colour and size matched to existing
vth	hooded ventilated roof tile, colour and size matched to existing
vs	ventilation stack. black
svs	ventilation stack. polished stainless steel
(single g replaced	existing windows are generally timber frames with leaded glazing glazed) and fine painted metal sashes. some metalwork has been d with painted timber to mimic the original sash.
simpler	north and the west elevations of the main house the windows are with single glazing and painted timber frames. there are a pair o metal frame windows on the north elevation
	per casement windows found on the annexe will be replaced by file double glazed units with an anodised bronzed aluminum fram
window repairec	building fabric and structure, including roofs, tiling, masonry, s, and rainwater goods are to be maintained and l/refurbished where necessary. the conditions survey will form th om which the maintenance works will be scheduled and agreed.
	repairs as
make	iopulo do

BOWKER SADLER PARTNERSHIP LIMITED

THIS DRAWING IS THE SUBJECT OF COPYRIGHT WHICH VESTS IN

BOWKER SADLER PARTNERSHIP LIMITED. IT IS AN INFRINGEMENT

OF COPYRIGHT TO REPRODUCE THIS DRAWING, BY WHATEVER MEANS, INCLUDING ELECTRONIC, WITHOUT THE EXPRESS WRITTE

new retaining structure, angled to follow the land form

DATUM 83.000

REV F1 19 Jul 2023 GMcG Minor Material Ammendment Application to include dormer structures at the rear of the annex is added to the drawing REV F 09 Mar 2022 GMcG The previously approved scheme (scheme 2) is altered to include a number of minor, non material amendments. the amendments included mostly rationalise the alterations at Rev E REVE 06 Sep 2021 GMcG The previously approved scheme (scheme 2) is altered to include a number of small amendments. **REV D** spare REV C 15 Jan 2021 GMcG Planning Application further revised, in response to planning and conservation officers comments REV B 10 Aug 2020 GMcG Revised Planning Application marked at Revision B REV A 05 Dec 2019 GMcG riginal Planning Applica REV. DATE DRN. CHKD. ROJECT The Hoo, Scheme 3 17 Lyndhurst Gardens, Hampstead, London Returning A Grand Victorian House To Private Domestic Accommoda LIENT Mr and Mrs Yu REPRESENTED BY JAGA Developments (London) North and West Elevations as Proposed SCALE SHEET SIZE DRAWN CHECKED DATE 1:50 @ A0 GMcG Oct 2019 BOWKER SADLER ARCHITECTURE : Hatherlow House, Hatherlow, Romiley, Stockport SK6 3DY Г: 0161 406 7333 : bsp@bowker-sadler.co.uk

DATUM 83.000

REVISION DRAWING No 19013 1141 TATUS PLANNING

N: www.bowker-sadler.co.uk