


- MINIMUM PLATE THICKNESS TO BE 10mm UNLESS NOTED



ALTERATIONS TO EXISTING LOW LEVEL PLATFORM FOR CHILLER REPLACEMENT ON

Originated :		Date:	
	SG		MAR 2023
Checked:		Date:	
			MAR 2023