
Keats House, Front Wall, NW3 2RR

Notes:

1. NOT FOR CONSTRUCTION.Do not measure from this drawing. All dimensions to be verified on site. Please note that for any construction, demolition, fitting, installation etc., pricing or costing a detailed survey of the related work is to be taken.

2. This is an indicative proposal only and subject to all statutory requirements. Input will be required from Structural and MEP engineers.



Front Entrance Balustrade








Rear Veranda

Paul Vick | Architects







Timber posting looks like metal

757 AP_003

Nov 2020

Keats House, Front Wall, NW3 2RR

Notes:

1. NOT FOR CONSTRUCTION.Do not measure from this drawing. All dimensions to be verified on site. Please note that for any construction, demolition, fitting, installation etc., pricing or costing a detailed survey of the related work is to be taken.

2. This is an indicative proposal only and subject to all statutory requirements. Input will be required from Structural and MEP engineers.





20x20mm Vertical Poles



Library Gates

Paul Vick | Architects





757 AP_004


Keats House, Front Wall, NW3 2RR

Notes:

1. NOT FOR CONSTRUCTION.Do not measure from this drawing. All dimensions to be verified on site. Please note that for any construction, demolition, fitting, installation etc., pricing or costing a detailed survey of the related work is to be taken.

2. This is an indicative proposal only and subject to all statutory requirements. Input will be required from Structural and MEP engineers.





The Freemason's Arms



St John's Church 002 (See also P.V.Architects' Historic Development Report AP_073)

Paul Vick | Architects



757 AP_005