

Montague Street (No. of Trees: 32)

Tree No (old tag)	Vegetation type	Species	No. of stems	Height (m)	Crown spread	DBH (cm)	Life stage	Vitality	Physiological Condition	Structural Condition	Safe Life Expectancy	Access	CAVAT value (£)/ Crown area (m2)
T4 (n/a)	Tree	1 Morus nigra Black Mulberry	1	8.0	8.0	30	Mature	High	Good	Fair	20-40 yrs	Good	£13905.31 / n/a
Site Features	Targets	Conditions	Notes									Survey date/ Surveyor	
	Footpath within crown spread.	Arboricultural work - Recent. Branch weight - Heavy. Crown reduction - Historic. Epicormic growth - Base / bole / principal stems. Fused limb / limbs. Leaning trunk - Minor. Pruning wounds - Historic. Root damage - Evident / observed. Exposed roots. Structural impact - Footpath / highway / drive disturbance. Suppressed crown - Minor. Unbalanced crown - Minor.	Possible recent root plate movement (soild crack) Recently proppedW3W: 2									2023-11-06. /James Chambers.	
Recommendation	- Lift low canopy - Pedestrian clearance to 3-4m over footpaths, removing low, pendulous growth only.						Purpose of works	- Appropriate			Safety Action Date	10/05/24	
Risk assessed	1.8						Risk of harm range				Risk category		

Tree No (old tag)	Vegetation type	Species	No. of stems	Height (m)	Crown spread	DBH (cm)	Life stage	Vitality	Physiological Condition	Structural Condition	Safe Life Expectancy	Access	CAVAT value (£)/ Crown area (m2)
T23 (n/a)	Tree	1 Sophora japonica Japanese Pagoda Tree	1	16.0	12.0	45	Mature	Moderate	Fair	Fair	20-40 yrs	Good	£31286.94 / n/a
Site Features	Targets		Conditions				Notes					Survey date/ Surveyor	
	Building within crown spread. Footpath within crown spread.		Buttresses / buttress roots - Minor adaptive growth / moderate development. Crown conflict - Structure / boundary / wire / tree. Crown reduction - Recent. Decay / structural defect in crown limb / limbs - Localised. Deadwood - Minor. Epicormic growth - Crown. Fork - Suspected structurally sound. Fused limb / limbs. Pruning wounds - Historic. Structural impact - Footpath / highway / drive disturbance. Suppressed crown - Minor. Unbalanced crown - Minor.				syn. Styphnolobium japonicum 07/11/23 branch tips in contact with building and young trees below.W3W: 6					2023-11-07. /James Chambers.	
Recommendation	<p>- Prune from adjacent structure to clear buildings by 1-2m, final cuts to be <5cm diameter, at suitable growth points, retaining furnishing growth to minimise visual impact.</p> <p>- Prune from adjacent tree to clear above cherry trees below crown, removing conflict and allowing more light and room for groups. Consider removal of the lowest branch to the north.</p>						Purpose of works	<p>- Necessary</p> <p>- Good Arboricultural Practice</p>		Safety Action Date	11/05/24 11/05/24		
Risk assessed	2						Risk of harm range			Risk category			