



Existing or new copings are to have 4mm stainless steel pins, resin fixed to the underside (4No per coping) and grouted into holes in the top of the sloping walls.

__в∏

Cracking in the outer or inner face of the chimney are to be repaired by inserting 4mm stainless steel 'Helibars' across the crack in accordance with manufacturers requirements.

— Existing or new copings are to have 4mm stainless steel pins, resin fixed to the underside (4No per coping) and grouted into holes in the top of the sloping walls.

0 C).5	1	2	3m	
					\checkmark
No	Date	Ву	Comments		
Issued	1				
Statu	s	Purpose of Issue			
-		PLANNING			
		/		1	
Da Unit 1	nnatt 1 The Wi	reworks 77	son Archit	eet London SE1 0E	SU
Ro	of P	lans			
Draw	Drawing Number				
658a-BM-DJA-DR-A-10001					-
RIBA	Stage	DJA Ref	Scale(s)		
-	-	658a	1:50		