


# Location Plan of Interim Taxi Rank

## Key

Existing Grade II listed railings in East Garden.



Section of Grade II listed railing to be reinstated and repaired. These are E/27 and E/28.



Item	Description	Quantity	Unit	Notes
010	MTR Tranche 3A Detailed Overlay BIC Floor	1.00	sqm	
011	MTR Tranche 3A Detailed Overlay BIC Floor	1.00	sqm	
012	MTR Tranche 3A Detailed Overlay BIC Floor	1.00	sqm	
013	MTR Tranche 3A Detailed Overlay BIC Floor	1.00	sqm	
014	MTR Tranche 3A Detailed Overlay BIC Floor	1.00	sqm	
015	MTR Tranche 3A Detailed Overlay BIC Floor	1.00	sqm	
016	MTR Tranche 3A Detailed Overlay BIC Floor	1.00	sqm	
017	MTR Tranche 3A Detailed Overlay BIC Floor	1.00	sqm	
018	MTR Tranche 3A Detailed Overlay BIC Floor	1.00	sqm	
019	MTR Tranche 3A Detailed Overlay BIC Floor	1.00	sqm	
020	MTR Tranche 3A Detailed Overlay BIC Floor	1.00	sqm	
021	MTR Tranche 3A Detailed Overlay BIC Floor	1.00	sqm	
022	MTR Tranche 3A Detailed Overlay BIC Floor	1.00	sqm	
023	MTR Tranche 3A Detailed Overlay BIC Floor	1.00	sqm	
024	MTR Tranche 3A Detailed Overlay BIC Floor	1.00	sqm	
025	MTR Tranche 3A Detailed Overlay BIC Floor	1.00	sqm	
026	MTR Tranche 3A Detailed Overlay BIC Floor	1.00	sqm	
027	MTR Tranche 3A Detailed Overlay BIC Floor	1.00	sqm	
028	MTR Tranche 3A Detailed Overlay BIC Floor	1.00	sqm	
029	MTR Tranche 3A Detailed Overlay BIC Floor	1.00	sqm	
030	MTR Tranche 3A Detailed Overlay BIC Floor	1.00	sqm	



Infill piece to be installed, cold repaired / welded to existing panel



Weld missing panel section

This document has been embedded within 1CP01-MDS-SE-REP-SS08\_SL31-000001 for information only and is not for HS2 acceptance or implementation.