

PROPOSED QUANTITY: 1

9200 mm



300 mm depth

EXISTING



MOCK UP



REMEDIAL ACTIONS	ON-SITE TASKS	ACTION BY		NOTES
		MX	OTHERS	
	REMOVE EXISTING SIGNAGE	X		Technical survey recommend fixing rail top and bottom.
	GLASS PANEL CLEANING			Front panel with return top and bottom, hook over rails to fix to top and bottom.
	PATCH & REPAIR SURFACE PAINTWORKS	X		Internal illumination on back tray behind the fascia.
	SPECIAL WORKS (STATE IN NOTES)			Owner confirmed the square sign to be removed in communications on 12/2/24, to be disconnected from fascia box.
	ELECTRICAL SUPPLY WORK		X	
INSTALLATION ACTIONS	INSTALLATION	X		
	INSTALLATION WITH GROUND SLEEVES			
	RETURN LANDSCAPING			
	TECHNICAL SURVEY FOR FUTURE REPLACEMENT COVER HOLES	X		