



- Emergency lighting
- * Fire safety signs

'Simultaneous Evacuation Strategy' in place

Replace all lobby doors with new FD30 doors. New doors to be of panelled design with heritage brass fire-rated hinges and smoke seals

Classification B:s1:d0 spread of flame protection Envirograf - 2xcoats Q/VFR/C (clear) fire rated @10m2 per litre per coat. Supplied as 50% requirement labelled C1 (1st coat) and 50% labelled C2 (2nd coat). No need for top coat to ceiling but yes to walls to protect against wear/day

Existing studwork/panelling partition to be 30FR - applied to the room side of the wall, party to the communal escape route. Door FR30 upgrade

Upgrade detail FD30 with door closer & smoke seals FD30 with smoke seals only. Door closers could be added for additional protection

FLATS GENERALLY:

strip out

Notes

KEY

- * drainage provision as existing
- * new plumbing/electrical systems
- * new fittings & finishes in kitchens * new fittings & finishes in bathrooms. Where panelling exists, to be lined with Aquapanel board -
- or similar and tiles). new meters to each flat
- * new lighting circuits & fittings
- * after repairs are carried out redecorate walls, ceilings and internal joinery throughout.

REPAIRS - GENERALLY:

*Floorboards: lift up floorboards to repair/fill in gaps

*Stairwell: repair to steps, handrails *Stairwell panelling: repairs prior to any fire proofing

*Windows: overhaul/draughtstripping (additional allowance for secondary glazing)

*Doors: repair & refurbish in accordance to the fireproofing strategy. Refer to Door Schedule

*Fireplaces not to be brought back in use. Reinstate surrounds, grates and hearths for aestethic purposes only

*All internal panelling where exposed within flats repair prior to any fire proofing.

*Cornices/skirtings repair (where missing sections, or redundant sockets are removed, intersection with unsympathetic cabling/pipework...) & make good

*Ceilings: lath & plaster repairs. Some rooms have artex, it may be more economical to leave (if without asbestos).

Annotations revised Heating system updated 17/05/2024 10/05/2024

Revisions

PLANNING

45 Great Ormond Street London, WC1N 3HZ

Proposed Sections C and D

ROGER MEARS ARCHITECTSLLP

Union Chapel, Compton Avenue

rma@rmears.co.uk tel 020 7359 8222

05/04/2024 1:100@A3 1:50@A1 Job No. 2203 **L (45)105** B