Application No.	Consultoes Names	Dagaiyad	Comment	Despared	Printed on:	05/08/2024	09:10:08
Application No: 2024/2613/P	Consultees Name: Manuela Simonetti	Received: 04/08/2024 16:08:28	Comment: INT	Having read the report by Jas Design / AF Acoustics, in which it is stated that 5.4.1 The closest windows with the potential to be affected by noise from the propose installation have been identified as belonging to the rear elevation of 59 Hillfield Road. These first floor windows are located at an approximate distance of 8m. 5.4.2 The windows belonging to 55 Hillfield Road will be completely screened from the installation. Having regard to the recommendations suggested by AF Acoustic (which excludes lit recommendations not be implemented) that to meet the requirements of Camden Lord the enclosure proposed for the air conditioning unit should utilise acoustic louvres capacoustic losses proposed in the project (see project specs) and that specific measure implemented to reduce vibration noise propagation, And having regard to the fact that the current boyler room of 57 Hillfield Road, erecter wall of 59 Hillfield (no notice given), together with the flue pipe discharging right next is currently operating at a noise level of above 50 decibles during the night, seriously enjoyment of both ground and first floor bedrooms in the rear extension of 59 Hillfield affecting the resident's mental health due to protracted insomnia caused by such boy And in view of the fact that it is a condition that the windows from 55 will be completed plant installation, as the owner-occupier of 59 Hillfield Road I kindly ask to: make it a condition to ensure that the windows of 59 will be completely screened from the installation, as much as number 55 are,	ed plant d. de plant diability should ndon Borough pable of achie es will need to d right agains to our 2nd flo comprimising Road, and d der room nois ly screened fi	such n Council, eving the b be st the border or window, g the angerously e, rom the	07.10.08
				and that the current boyler room be thoroughly acoustically insulated as well, in order noise propagating to 59 Hillfield and restore the full enjoyment of the concerned bedra		the current	