

Application No:	Consultees Name:	Received:	Comment:	Response:
2024/3306/P	John	07/09/2024 09:48:14	INT	These exhaust outlets should be closed and internal extractor units in the kitchens installed. Internal extractor units are a much more sensible option in this location. The noise and fumes from the exhaust outlets is detrimental to residents living a few metres above them and they should be closed off.
