

5. All temporary works to be responsibility of the contractor.

This drawing to be read in conjunction with all relevant Architect's drawings and specifications and with other Consultant's Information.

Cocoa 406, The Biscuit Factory, SE16 4DG
020 7928 8787 studio@new-works.net
new-works.net
© New works (Architecture) Ltd

1915 (PL)210 DATE 23.08.24