

<b>Application No:</b>	<b>Consultees Name:</b>	<b>Received:</b>	<b>Comment:</b>	<b>Response:</b>
2024/3851/P	Elizabeth Rollo-Walker	01/10/2024 12:13:44	COMMNT	Regarding this application can I please ask that a full ground survey is undertaken before any building takes place. The Cottage in Hilltop Road has a large crack running through it top to bottom which does not appear to be tree related so suggests that there may be ground movement. In addition the garden walls of 2 and 4 Hilltop Road fell down last Autumn with no apparent cause so feel that the ground here needs to be checked. 2 Hilltop Road had a significant amount of subsidence work undertaken some 30 years ago and I worry that yet more building could have a detrimental effect on the ground.

---

**Total: 2**