



- Notes
1. T&G cladding / lining
 2. weatherboarding
 3. stair string?
 4. Exidence of removed partition? weatherboarding (not surveyed; concealed behind linings at floor below)
 - 5.

P1 16/05/2024 DJG

revisions:

All dimensions and areas are approximate and are to be verified.

NORTON MAYFIELD ARCHITECTS

Harland Works, Unit 8
70 John Street
Sheffield
S2 4QU
Tel: 0114 270 0014
nortonmayfield.co.uk

RIBA | Chartered Practice **arb** | Architects Registration Board

Client:

Mr. D. Jordan

Project:

85 Heath St & 6 Golden Yard London NW3 6UG

Drawing No:

1955-NMA-XX-01-DR-A-00601

Drawing title:

Existing Stair Opening Up

Status: S2 Revision: P1 Purpose of issue: For Information Scale:

Heath St floor.vwx