#### D.1 TRIAL REPAIRS REVIEW


D.1.1 Trial repairs were undertaken on March 5th and 6th, 2024 using limewash tinting over poorly matched repairs, and these trials were described in Section 3 of the Heritage Assessment.

D.1.2 This appendix reviews the repairs seven and a half months after completion.

D.1.3 The left-hand photos photos in the pages below show the repairs on March 16th, ten days after application, and the more recent photographs on the right-hand side were taken on October 23rd, 2024.



D.2.1 After seven and a half months there is no perceptable change to the repairs located under the window cill of House 5.



The repairs are almost imperceptable from the pavement which is the distance from which they are to be judged.

Photo of tinting repair taken on October 23rd, 2024.

#### **APPENDIX D: TRIAL REPAIRS REVIEW**



# APPENDIX D: TRIAL REPAIRS REVIEW

D.3 TRIAL 2

between House 5 and House 4.

D.3.2 After seven and a half months there is no perceptable change to the repairs located to the lower corner of the pier.



The corner repair after ten days on March 16. The side facing outwards is considered satisfactory, while the lateral face still has a strong contrast to the darker adjacent stone.

Photo of tinting repair taken on October 23rd, 2024.

D.3.1 An partially successful repair to the corner base of the column

# APPENDIX D: TRIAL REPAIRS REVIEW

D.4 TRIAL 3

5.

D.4.2 After seven and a half months there is no perceptable change to the repairs located on the corner of the basement pier.



The corner repair after ten days. This repair is considered satisfactory.



D.4.1 An successful repair to the corner pier in the basement area of House



# APPENDIX D: TRIAL REPAIRS REVIEW

D.5 TRIAL 4

House 5.

D.5.2 After seven and a half months there is no perceptable change to the repairs located on the corner of the basement window pier.



The corner repair after ten days. The repair is considered satisfactory.

D.5.1 An successful repair to the corner of a pier in the basement area of



Photo of tinting repair taken on October 23rd, 2024. The repair identification label is still in place.