

Application No:	Consultees Name:	Received:	Comment:	Response:
2024/4393/P	Araminta Critchley	05/11/2024 12:20:48	OBJ	Reject this as they will have a view straight into my living room
2024/4393/P	R Wells	05/11/2024 15:16:02	COMMNT	<p>1) The extension of 1.85m sets this back further than existing on the street as can be seen in the diagrams showing the 'block plan/location plan'. The description of it being 'minor' in section 6.32 of the heritage report is not taking into account that this is a creeping line further back than others that are referenced in adjoining/close proximity. The implied position in Section 6.25 that this somehow creates a more 'uniform' position is thus peculiar.</p> <p>2) Although not addressed in the documents submitted, existing tree(s) likely need cutting back and removing and there is no mention of replacement. We have already lost one large old tree on Murray Street due to rail bridge works recently with no apparent plan for replacement.</p> <p>3) The above reduces space/ability for water dissipation in event of heavy rain. Murray Street already has a high surface/flash flooding risk rating on Gov.UK and continuing to allow reductions in open space and foliage without addressing that, is increasing that risk.</p>