

UCL Teaching Spaces Chadwick building – External condenser replacement




Redundant External Daikin Condenser to be removed along with associated redundant pipework.



Proposed External Daikin Condenser to be installed in the same exact location with new pipework to follow existing routes and replace those pipes being removed

- Key
- Existing unit removed
 - Proposed new condenser unit location



UCL Teaching Spaces Chadwick building – External condenser replacement



Two redundant External Daikin Condenser units to be removed along with associated pipework fixed to the wall and existing gallow brackets



Proposed Single External Condenser unit to replace the redundant two units in the same location with new pipework to follow the exiting routes and new gallow brackets to level of bottom existing unit.

- Key
- Existing unit removed
 - Proposed new condenser unit location