



Section C-C West - Lodge Stone and Brick Repairs



Section D-D East - Lodge Stone and Brick Repairs



Section E-E East - Lodge Stone and Brick Repairs



© BOWKER SADLER PARTNERSHIP LIMITED

RESERVES ALL ITS RIGHTS

■ CHECK ALL DIMENSIONS ON SITE

■ THIS DRAWING IS THE SUBJECT OF COPYRIGHT WHICH VESTS IN BOWKER SADLER PARTNERSHIP LIMITED. IT IS AN INFRINGEMENT MEANS, INCLUDING ELECTRONIC, WITHOUT THE EXPRESS WRITTEN CONSENT OF BOWKER SADLER PARTNERSHIP LIMITED WHICH

BOWKER SADLER PARTNERSHIP LIMITED ASSERTS ITS RIGHTS TO


■ DRAWING TO BE READ IN CONJUNCTION WITH THE HEALTH AND SAFETY PLAN AND ALL RELEVANT RISK ASSESSMENTS

Survey drawings are kindly provided by Malcom Hughes Land Surveys Ltd and are assumed

BE IDENTIFIED AS THE AUTHOR OF THIS DESIGN

■ REPORT ERRORS & OMISSIONS TO ARCHITECT.

to accurately describe the existing buildings, services and external spaces.



A: Hatherlow House, Hatherlow, Romiley, Stockport SK6 3DY T: 0161 406 7333 E: bsp@bowker-sadler.co.uk W: www.bowker-sadler.co.uk

19013

3014

**PLANNING**