



Lead flashings to sky facing stonework of windows, pediments, and cornicing, either replaced or repaired as necessary.

-Mortar repairs carried out to stone pilaster

nadiments and sill stanswork	
pediments and cill stonework air to retained stonework of window	
	/ 24/01/2025 L.B.C. Issue. JKC JKC
	Rev.Date Notes Drawn Checked
	ARCHITECTS East Grinstead, West Sussex tel. 07495 980 757 jonathan@cerowski.co.uk
	client: University College School
	Project: Facade Repairs, UCS,
	Hampstead, NW3 6XH
	Drawing:
	Existing South Block, East Elevation
	Scale Drawn By Checked By Issued For 1:100@A3 JKC JKC Listed Building Consent
	Drawing No. Revision
	Drawing No. Revision /