



7 - South Existing Gates opening



8 - Weak & Gappy Vegetation



9 - Weakness often occurs near trees



10 - Area where weapons are often hidden



11 - Weakness often occurs near trees



12 - Weak & Gappy Vegetation



13 - Example of Vunrabilities from opportunist thieves

These are sample of many areas which need improving

Rev No.	Date	Description
<div>Notes:</div> <div>Any inaccuracies or errors to be reported to the architect/surveyor immediately and prior to anywork commencing. All dimensions to be verified on site. All work to comply with British Standards Code of practice. All external surfaces and materials to match existing. This drawing and all information provided within it is the copyright of UPP Consultants Ltd. and reproduction without prior consent is strictly forbidden.</div>		
Dwg No ECR-A-01-004	Drawn UPP	
Drawing Site photos	Checked UPP	
Scale @ A3	Issue Date 30.09.2024	
<div>Project Address</div> <div>The Etons, Eton College Road, NW3 2BT</div>		
Client Shellpoints Trustees Ltd (c/o Parkgate Aspen)	Status For Planning	