L/2012/27371/S/MLL/kh/nap

REF: TBA

POLICYHOLDER: Mr R B Goldstein

ADDRESS: 261 Goldhurst Terrace, London, NW6 3EP



PHOTOGRAPHS TAKEN DURING MONITORING INSPECTION ON 04 SEPTEMBER 2013



PHOTOGRAPH 01:

This photograph gives a general view of the rear elevation of the insured property showing the single storey extension and the London Plane tree.



PHOTOGRAPH 02:

This photograph gives a closer view of the extension.

L/2012/27371/S/MLL/kh/nap

REF: TBA

POLICYHOLDER: Mr R B Goldstein

ADDRESS: 261 Goldhurst Terrace, London, NW6 3EP

PHOTOGRAPHS TAKEN DURING MONITORING INSPECTION ON 04 SEPTEMBER 2013



PHOTOGRAPH 03:

This photograph shows the crack to the left side of the extension which has increased in width by 2mm.



PHOTOGRAPH 04:

This photograph gives a view of movement of the rear steps.

L/2012/27371/S/MLL/kh/nap

REF: TBA

POLICYHOLDER: Mr R B Goldstein

ADDRESS: 261 Goldhurst Terrace, London, NW6 3EP

GHG

PHOTOGRAPHS TAKEN DURING MONITORING INSPECTION ON 04 SEPTEMBER 2013




PHOTOGRAPH 05:

This photograph gives a view of movement of the brick paved path to the right side of the extension.



PHOTOGRAPH 06:

This photograph gives a view of the vertical crack internally to the right side of the extension at the junction with the main building.



PHOTOGRAPH 07:

This photograph gives a view of the crack towards the centre of the extension at the junction with the main building.

Horizon House, 22-24 Station Hill, Southampton Road, Eastleigh, SO50 9XB

The Graham High Group Limited, Registered In England, Company Registration No: 3007129 Registered office, c/o C.W. Fellowes Ltd, Templars House, Lulworth Close, Chandlers Ford, Hants SO53 3TL

L/2012/27371/S/MLL/kh/nap

REF: TBA

POLICYHOLDER: Mr R B Goldstein

ADDRESS: 261 Goldhurst Terrace, London, NW6 3EP

GHG

PHOTOGRAPHS TAKEN DURING MONITORING INSPECTION ON 04 SEPTEMBER 2013



PHOTOGRAPH 08:

This photograph shows the crack along the wall ceiling junction with the extension which has increased in width substantially.



PHOTOGRAPH 09:

This photograph gives a view of the crack to the left side of the extension at the junction with the main building also showing movement of the kitchen base units.



PHOTOGRAPH 10:

This photograph gives a view of the tiled floor which is somewhat uneven at the base of the stairs between the extension and main building.

Horizon House, 22-24 Station Hill, Southampton Road, Eastleigh, SO50 9XB

L/2012/27371/S/MLL/kh/nap

REF: TBA

POLICYHOLDER: Mr R B Goldstein

ADDRESS: 261 Goldhurst Terrace, London, NW6 3EP

GHG Chartened from Adjacters Subsidence Engineere

PHOTOGRAPHS TAKEN DURING MONITORING INSPECTION ON 04 SEPTEMBER 2013



PHOTOGRAPH 11:

This photograph gives a general view of the dining room within the extension extending through to the kitchen which is in the rear left corner of the main house.



PHOTOGRAPH 12:

This photograph gives a view along the rear of the extension showing the proximity of the large mature London Plane tree which is also very close to a neighbouring property.