



General notes:

- 1. Shading indicates new construction.
- All existing bathroom, kitchen and sanitaryware fittings to be removed. 2.

- Notes on Lower Ground Floor:
- Internal doors: S/F new traditionally detailed painted SW door and architraves throughout except where indicated otherwise.




Last saved on 06/09/2013 filename:w:\jobs\js27.02\drawings\work in progress\sheets layouts\2 general arrangement\2000 proposed lower ground floor plan.dwg by JXA






- 2.
- 3.
- 4.
- 5.
- 6.
- 7.
- 8.
- 9.



No.	NOTES (STATUS: F. FEASIBILITY S. SKETCH DESIGN P. PLANNING B. BUILDING CONTROL D. DE	ESIGN DEV /	PRELIM M. M	EASUR	REME	NT T. TENDER C. CONSTRUCTION R. RECORD)	DONALD INSALL ASSOCIA
1	For construction use only if status 'C' and checked against current revision						12 Devonshire Street London W1G 7AB Tel: 020 7245 9888 En
2	All dimensions to be checked on site by contractor						12 Devolusinire Street London W1G /AB 1ei: 020 /245 9888 En
3	Do not scale from this drawing						Job 27 John Street & 21 John's Mews
4	Unless otherwise indicated all dimensions are in millimetres						
		А	05/09/2013	JXA	ACS	Planning Issue	Title Proposed Ground Floor Plan
		А	29/08/2013	JXA	ACS	Adding Notes and alterations to layout	
		-	30/07/2013	JXA	ACS	Initial Issue	
		Rev	Date	Dwn	Auth	REVISIONS	


Last saved on 06/09/2013 filename:w:\jobs\js27.02\drawings\work in progress\sheets layouts\2 general arrangement\2001 proposed ground floor plan.dwg by JXA

Scale (A3) 1: 1 2



BASED ON SURVEY BY OTHERS

Last saved on 06/09/2013 filename:w:\jobs\js27.02\drawings\work in progress\sheets layouts\2 general arrangement\2002 proposed first floor plan.dwg by JXA



BASED ON SURVEY BY OTHERS


Last saved on 06/09/2013 filename:w:\jobs\js27.02\drawings\work in progress\sheets layouts\2 general arrangement\2003 proposed second floor plan.dwg by JXA

Job JS27.02	Status P			
No 2003	Rev A			
Scale (A3) 1:	1	2	5	

BASED ON SURVEY BY OTHERS

General notes:

- 1. Shading indicates new construction.
- All existing bathroom, kitchen and sanitaryware fittings to be removed. 2.
- Original joinery to be recorded and set aside for resue where removal necessary. 3.
- No original door survived throughout the house. New door details to follow those of DIA drawings. 4.
- Fireplaces and hearth surrounds to be retained unless noted otherwise. Existing chimney flues to be unblocked and lined. 5.
- 6. Existing services and drains removed and replaced throughout.
- 7. Overhaul and repair all windows/shutters and mouldings, including paneled aprons (except where stated as new items).
- 8. All rooms to be fitted with smoke/heat detectors and sounders at ceiling level with air sampling detection system in fine rooms
- Repair floor joists as necessary. Consult with Architect and Structural Engineer. Strengthen existing joists where new stone floor finish to be installed. 9
- 10. Provide new appropriately detailed and sized cornices of traditional design throughout to replace existing modern cornices.




©2013 DONALD INSALL ASSOCIATES LIMITED

Last saved on 06/09/2013 filename:w:\jobs\js27.02\drawings\work in progress\sheets layouts\2 general arrangement\2004 proposed third floor plan.dwg by JXA

Notes on Lower Ground Floor:

Internal doors: S/F new traditionally detailed painted SW door and architraves throughout except where indicated otherwise.




Job JS27.02	Status P				
^{No} 2004	Rev	А			
Scale (A3) 1:	1	2	5		

BASED ON SURVEY BY OTHERS

General notes:

- 1. Shading indicates new construction.
- All existing bathroom, kitchen and sanitaryware fittings to be removed. 2.
- Original joinery to be recorded and set aside for resue where removal necessary. 3.
- No original door survived throughout the house. New door details to follow those of DIA drawings. 4.
- 5. Fireplaces and hearth surrounds to be retained unless noted otherwise. Existing chimney flues to be unblocked and lined.
- 6. Existing services and drains removed and replaced throughout.
- 7. Overhaul and repair all windows/shutters and mouldings, including paneled aprons (except where stated as new items).
- 8. All rooms to be fitted with smoke/heat detectors and sounders at ceiling level with air sampling detection system in fine rooms
- Repair floor joists as necessary. Consult with Architect and Structural Engineer. Strengthen existing joists where new stone floor finish to be installed. 9.
- 10. Provide new appropriately detailed and sized cornices of traditional design throughout to replace existing modern cornices.



0	1	2	3	4	5	10 (m)


No.	NOTES (S	STATUS	S: F. FE	EASIBILITY S. SKETCH DESIGN P. PLANNING B. BUILDING	CONTROL D. DESIGN DEV /	PRELIM M. M	EASURI	EMEN	T T. TENDER C. CONSTRUCTION R. RECORD)	DONALD INSALL ASSOCIA
1	For constr	truction	use on	ly if status 'C' and checked against current revision						12 Devonshire Street London W1G 7AB Tel: 020 7245 9888 E
2	All dimens	sions to	be che	ecked on site by contractor						12 Devolsing Street London WIG /AB Tel: 020 /245 9888 EA
3	Do not sca	ale from	this di	rawing						Job 27 John Street & 21 John's Mews
4	Unless oth	herwise	indicat	ted all dimensions are in millimetres						
					А	05/09/2013	JXA	ACS	Planning Issue	Title Proposed Fourth Floor Plan
					А	29/08/2013	JXA	ACS	Adding Notes and alterations to layout	
					-	30/07/2013	JXA	ACS	Initial Issue	
					Rev	Date	Dwn	Auth	REVISIONS	

©2013 DONALD INSALL ASSOCIATES LIMITED

Last saved on 06/09/2013 filename:w:\jobs\js27.02\drawings\work in progress\sheets layouts\2 general arrangement\2005 proposed fourth floor plan.dwg by JXA

Notes on Lower Ground Floor:

Internal doors: S/F new traditionally detailed painted SW door and architraves throughout • except where indicated otherwise.






IATES LIMITED

Email: london@insall-architects.co.uk

Job JS27.02	Status P			
^{No} 2005	Rev A			
Scale (A3) 1:	1	2	5	


CHARTERED ARCHITECTS PLANNING CONSULTANTS



0 1 2 3 4 5 10 (m)

No.	NOTES (S	STATU	S: F. FI	EASIBILITY S. SKETCH DESIGN P. PLANNING B. BUILDING	G CONTROL D. DESIGN DEV /	PRELIM M. M	EASUR	EMEN	T T. TENDER C. CONSTRUCTION R. RECORD)	DONALD INSALL ASSOCIA
1	For const	struction	use on	ly if status 'C' and checked against current revision						12 Devonshire Street London W1G 7AB Tel: 020 7245 9888 En
2	All dimen	nsions to	be ch	ecked on site by contractor						12 Devolusini e Street London WIG /AD Tel: 020 /245 9000 En
3	Do not sca	cale from	n this d	rawing						Job 27 John Street & 21 John's Mews
4	Unless oth	therwise	indica	ted all dimensions are in millimetres						
					А	05/09/2013	JXA	ACS	Planning Issue	Title Proposed Roof Plan
					А	29/08/2013	JXA	ACS	Adding Notes and alterations to layout	
					-	30/07/2013	JXA	ACS	Initial Issue	
					Rev	Date	Dwn	Auth	REVISIONS	

Last saved on 06/09/2013 filename:w:\jobs\js27.02\drawings\work in progress\sheets layouts\2 general arrangement\2006 proposed roof plan.dwg by JXA



Last saved on 05/09/2013 filename:w:\jobs\js27.02\drawings\work in progress\sheets layouts\2 general arrangement\2200 front elevation.dwg by JXA

General Notes on Repairs:

Brickwork

- Carefully rake out damaged joints and re-point where • necessary in matching mortar.
- Carefully brush clean brickwork to remove moss and staining where necessary.
- Replace mismatching brickwork with second hand bricks to match existing - sample must be approved by Architect
- Soot down any repairs to match existing. ٠

Stone

Carefully brush clean stonework - remove moss and • stain and repoint as necessary.

Leadwork


Carefully investigate roof leadwork once safe access is • established, and repair/replace as necessary all in accordance with Lead Sheet Association's recommendations.

Drainage

- ٠ Remove redundant services.
- Repair/replace damaged pipes as necessary.
- Clear all the blockages .
- All the external rainwater and soil vent pipes are to be replaced in cast iron to match existing.
- All internal soil vent pipes must be adequately sound insulated and properly concealed, and to follow existing service route where possible.

CHARTERED ARCHITECTS PLANNING CONSULTANTS

Job JS27.02	Status P			
No 2200	Rev A			
Scale (A3) 1:	1	0	0	



Last saved on 05/09/2013 filename:w:\jobs\js27.02\drawings\work in progress\sheets layouts\2 general arrangement\2201 rear elevation.dwg by JXA

General Notes on Repairs:

Brickwork

- Carefully rake out damaged joints and re-point where • necessary in matching mortar.
- Carefully brush clean brickwork to remove moss and staining where necessary.
- Replace mismatching brickwork with second hand bricks to match existing - sample must be approved by Architect
- Soot down any repairs to match existing.

Stone

Carefully brush clean stonework - remove moss and ٠ stain and repoint as necessary.

Leadwork

Carefully investigate roof leadwork once safe access is • established, and repair/replace as necessary all in accordance with Lead Sheet Association's recommendations.

- Remove redundant services. ٠
- Repair/replace damaged pipes as necessary.
- Clear all the blockages
- All the external rainwater and soil vent pipes are to be replaced in cast iron to match existing.
- All internal soil vent pipes must be adequately sound insulated and properly concealed, and to follow existing service route where possible.

CHARTERED ARCHITECTS PLANNING CONSULTANTS

Job JS27.02	Status P			
No 2201	Rev A			
Scale (A3) 1:	1	0	0	

- ٠
- Carefully brush clean brickwork to remove moss and staining where • necessary.
- Replace mismatching brickwork with second hand bricks to match ٠ existing - sample must be approved by Architect ٠
- Stone •
- Leadwork
- Drainage ٠
- ٠ •
- •
- .






NOTES (STATUS: F. FEASIBILITY S. SKETCH DESIGN P. PLANNING B. BUILDING CONTROL D. DESIGN DEV / PRELIM M. MEASUREMENT T. TENDER C. CONSTRUCTION R. RECORD)

Α

А

Rev



DONALD INSALL ASSOCIATES LIMITED

12 Devonshire Street London W1G 7AB Tel: 020 7245 9888 Email: london@insall-architects.co.uk

Job 27 John Street & 21 John's Mews

Title Proposed Front & Rear Mews Elevation

notes on windows in Mews

- remove existing boading and replace with lead ٠
- remove existing modern metal windows and replace with new sash ٠ windows with traditionally detailed painted timber double glazed windows

©2013 DONALD INSALL ASSOCIATES LIMITED

Do not scale from this drawing

For construction use only if status 'C' and checked against current revision

All dimensions to be checked on site by contractor

4 Unless otherwise indicated all dimensions are in millimetres

No.

1

2 3

Last saved on 05/09/2013 filename:w:\jobs\js27.02\drawings\work in progress\sheets layouts\2 general arrangement\2202 proposed front & rear mews elevation.dwg by JXA

05/09/2013 JXA ACS Planning Issue

29/08/2013 JXA ACS Adding Notes

01/08/2013 AXT ACS Initial Issue Date Dwn Auth REVISIONS

repair and stitch existing

crack

General Notes on Repairs:

Brickwork

- Carefully rake out damaged joints and re-point where necessary in matching mortar.
- Soot down any repairs to match existing.

Carefully brush clean stonework - remove moss and stain and repoint as necessary.


• Carefully investigate roof leadwork once safe access is established, and repair/replace as necessary all in accordance with Lead Sheet Association's recommendations.

- Remove redundant services.
- Repair/replace damaged pipes as necessary.
- Clear all the blockages
- All the external rainwater and soil vent pipes are to be replaced in cast iron to match existing.
- All internal soil vent pipes must be adequately sound insulated and properly concealed, and to follow existing service route where possible.


JS27.02	C.	Status P			
No 2202	I	Rev A			
Scale (A3) 1	l:	1	0	0	

CHARTERED ARCHITECTS

PLANNING CONSULTANTS



Last saved on 06/09/2013 filename:w:\jobs\js27.02\drawings\work in progress\sheets layouts\2 general arrangement\2300 proposed section a.dwg by JXA



Last saved on 06/09/2013 filename:w:\jobs\js27.02\drawings\work in progress\sheets layouts\2 general arrangement\2301 proposed section b.dwg by JXA

JS27.02	P			
No 2301	Rev	В		
Scale (A3) 1:	1	2	5	