





ELEVATION



SECTION

PLAN



Notes

- ① Existing brick wall to be cleaned.
- ② Existing windows to be removed and replaced with steel framed units.
- ③ Existing steel lintel to be refurbished.

Bennetts Associates Architects

1 Rowstone Place London EC1V 7HL
T +44 (0)20 7520 3300 F +44 (0)20 7520 3333
E mail@bennettsassociates.com

For Bennett's Associates Architects Limited, London
www.bennettsassociates.com

Project 1215 Project No. 1215

RCophth
Royal College of Ophthalmologists

Drawing Title
Cladding Bay Study 2
South Elevation, Typical Window

Drawing Number
1215_P20_402

Revision
1

Scale @ A3 1:40 Scale @ A1 1:20 Revision Date
130129
TY MAR 00