brick repair 'like for like' re-using existing bricks with mortar to match determined by laboratory analysis

safety gate and railing to comply with building control requirements, section sizes and details as existing handrail

reeded glass retained in-situ to obscure view of lobby enclosure behind

existing glass in vertical panel to side of existing door replaced with painted panel set within retained timber framing

new connection into SVP from relocated staff WC