




TREATMENT OF DRY RISER INLET CUPBOARD : PRECEDENTS



FRONT ELEVATION : DRY RISER INLET LOCATION

