

**Michael Honeyfield and Associates***Engineering & Building Consultants*

Summit House  
2 Highfield Road  
Dartford, Kent DA1 2JY  
Tel: (01322) 289587 (2 lines)  
Fax: (01322) 271533  
E-mail: mhoneyfield@aol.com

DOCUMENT 3  
DRAIN DAMAGE

Our Ref: 12/02/3135  
Your Ref:  
Date: 4<sup>TH</sup> June 2003

Mrs G Singer  
Basement Flat  
147 Goldhurst Terrace  
London NW6


Dear Mrs Singer,

**RE: INSURANCE CLAIM:~  
147 GOLDHURST TERRACE, LONDON NW6.**

Further to our recent telephone conversation, we confirm that insurers have agreed drainage repairs at your property, and we have requested that the contractors "Soiltec" contact you to arrange a date for the work to be undertaken.

As you are aware we have strongly recommended that the mature tree close to your property is extensively cropped to restrict further root damage. Your loss adjuster, Mr Bickley, has informed the writer that this is not a insurable item. Will you please confirm your intentions to this item.

Yours sincerely  
**FOR MICHAEL HONEYFIELD & ASSOCIATES**



*Michael Honeyfield*

c.c. Mr John Bickley ~ Ref 02/4229/J.B./J.J.



Soiltec Laboratories Limited,  
Ledian Farm Industrial Estate,  
Upper Street, Leeds,  
Maidstone, Kent ME17 1RZ  
Telephone: (01622) 861350  
Fax: (01622) 862752  
E-mail: info@soiltec.co.uk  
Web Site: www.soiltec.co.uk

## QUOTATION

Michael Honeyfield & Associates  
Summit House  
2 Highfield Road  
Dartford  
Kent  
DA1 2JY

Quotation No. 00910/9  
Your ref: 112/02/3135  
Contract Ref: London NW6  
Date: 19<sup>th</sup> May 2003

DOCUMENT  
3 DRAIN  
DAMAGE

For the attention of Mr M Honeyfield

Dear Sir

Re: 147 Goldhurst Terrace, London NW6

Quotation for drainage remedial repairs at the above property:

- 01 Manhole 1 connection A to WC: Excavate/replace from Manhole to WC. Replace rest bend. Provide new connection to existing WC. Excavation will breach footings. A pre-stressed lintel may be required to support footings.
- 02 Manhole 1 connection B to Gully: Excavate/replace from Manhole to Gully. Replace Gully. Provide suitable benching/kerbing for Gully.
- 03 Manhole 1 connection C to Soil Waste Vent Pipe: Excavate/replace from Manhole to Soil Waste Vent Pipe. Replace Rest Bend.

All replacement pipe to be laid in suitable diameter plastic drainage pipe and associated fittings. Bed with pea shingle. Backfill with suitable, selected, compactable as dug spoil. Re-instate surface to match existing cover/levels.

### Totals

Item 01	433.13
Item 02	315.00
Item 03	219.38

**TOTAL** £ 967.51 + VAT

All quotations are subject to our general terms and conditions of business. All prices are valid for 30 days from the date of our quotation. If any of the above items are omitted from the Contract, we reserve the right to re-quote for items required.