

## Emplan Limited Window Replacement Schedule



<b>Project:</b>	<b>Shaftesbury Theatre External Works</b>
<b>Date:</b>	<b>21/04/2010</b>

**Please Note: This schedule is to be read in conjunction with our window elevation drawings (ref: EPL/ST/101 & 102).**

**All existing frames are to be striped back to bare timber, and receive 1 coat of primer, 1 undercoat, & 2 top coats.**

<u>Unit No.</u>	<u>Location</u>	<u>Description</u>	<u>Glass Required</u>	<u>Remarks</u>
1	HH;3rd	Replace existing casement sash & make good frame (All), new beading to all sections.	2no panes	Window furniture not surveyed
2	HH;3rd	Replace existing casement sash & make good frame (All), new beading to all sections.	Grille	Window furniture not surveyed
3	HH;3rd	Replace existing casement sash & make good frame (All), new beading to all sections.	1no pane	Window furniture not surveyed
4	HH;3rd	Replace existing casement sash & make good frame (All), new beading to all sections.	1no pane	Window furniture not surveyed
5	HH;3rd	Replace existing casement sash & make good frame (All), new beading to all sections.	1no pane	Window furniture not surveyed
6	HH;3rd	Replace existing casement sash & make good frame (All), new beading to all sections.	None	Window furniture not surveyed
7	HH;3rd	Replace existing casement sash & make good frame (All), new beading to all sections.	None	Window furniture not surveyed
8	HH;3rd	Replace existing 2 middle casement sashes & make good frame (All), new beading to all sections.	2no panes	Window furniture not surveyed
9	HH;3rd	Replace existing aluminium sash & make good frame (All), new beading to all sections.	Clear	Window furniture not surveyed
10	HH;3rd	Replace existing casement sash & make good frame (All), new beading to all sections.	8no panes	Window furniture not surveyed
11	HH;3rd	Replace existing aluminium sash & make good frame (All), new beading to all sections.	Clear	Window furniture not surveyed
12	HH;3rd	Replace existing L/H/S casement sash & make good frame (All), new beading to all sections.	2no panes	Window furniture not surveyed
13	HH;3rd	Replace existing window with new, new beading to all sections.	1no window	Window furniture not surveyed
14	HH/BS;3rd	Replace existing casement sash & make good frame (All), new beading to all sections.	1no window	Window furniture not surveyed
15	BS;3rd	Replace existing casement sash & make good frame (All), new beading to all sections.	6no panes	Window furniture not surveyed
16	BS;3rd	Replace existing 2 middle casement sashes & make good frame (All), new beading to all sections.	6no panes	Window furniture not surveyed
17	BS;3rd	Make good frame (All).	None	Window furniture not surveyed
18	BS;3rd	Make good frame (All).	None	Window furniture not surveyed
19	BS;3rd	Make good frame (All).	None	Window furniture not surveyed

20	BS;3rd	Replace existing 2 middle casement sashes & make good frame (L&R/H/S), new beading to all sections.	8no panes	Window furniture not surveyed
21	BS;3rd	Replace existing window with new, new beading to all sections.	1no window	Window furniture not surveyed
22	BS;1st	Replace 2no existing casement sash & make good frame (All), new beading to all sections.	None	Window furniture not surveyed
23	BS;2nd	Replace existing casement sash & make good frame (All), new beading to all sections.	None	Window furniture not surveyed
24	BS;2nd	Replace 2no existing casement sash & make good frame (All), new beading to all sections.	None	Window furniture not surveyed
25	BS;2nd	Replace existing casement sash & make good frame (All), new beading to all sections.	None	Window furniture not surveyed
26	BS;2nd	Replace existing casement sash & make good frame (All), new beading to all sections.	None	Window furniture not surveyed
27	BS;2nd	Replace existing casement sash & make good frame (All), new beading to all sections.	1no window	Window furniture not surveyed
28	BS;1st	Replace existing casement sash & make good frame (All), new beading to all sections.	None	Window furniture not surveyed
29	BS;1st	Replace 2no existing casement sash & make good frame (All), new beading to all sections.	2no panes	Window furniture not surveyed
30	BS;1st	Replace existing casement sash & make good frame (All), new beading to all sections.	None	Window furniture not surveyed
31	BS;1st	Replace 2no existing casement sash & make good frame & fanlights (All), new beading to all sections.	None	Window furniture not surveyed
32	HH/BS;1st	Replace 2no existing casement sash & make good frame & fanlights (All), new beading to all sections.	None	Window furniture not surveyed
33	HH;1st	Replace 2no existing casement sash & make good frame & fanlights (All), new beading to all sections.	None	Window furniture not surveyed
34	HH;2nd	Replace existing casement sash & make good frame & fanlight (All), new beading to all sections.	None	Window furniture not surveyed
35	HH;2nd	Replace existing casement sash & make good frame & fanlight (All), new beading to all sections.	None	Window furniture not surveyed
36	HH;2nd	Replace existing casement sash & make good frame & fanlight (All), new beading to all sections.	None	Window furniture not surveyed
37	HH;2nd	Replace existing casement sash & make good frame & fanlight (All), new beading to all sections.	None	Window furniture not surveyed
38	HH;2nd	Replace existing casement sash & make good frame & fanlight (All), new beading to all sections.	None	Window furniture not surveyed
39	HH;2nd	Replace existing casement sash & make good frame (All), new beading to all sections.	3no panes	Window furniture not surveyed
40	HH;2nd	Replace 2no existing casement sash & make good frame (All), new head & beading to all sections.	None	Window furniture not surveyed
41	HH;2nd	Replace existing casement sash & make good frame (All), new beading to all sections. Clean spray paint off inside of glass.		Window furniture not surveyed
42	HH;2nd	Replace existing casement sash & make good frame & fanlight (All), new beading to all sections.	None	Window furniture not surveyed
43	HH;2nd	Replace 2no existing casement sash & make good frame & fanlights (All), new beading to all sections.	1no window	Window furniture not surveyed
44	HH;2nd	Replace existing casement sash & make good frame & fanlight (All), new beading to all sections.	None	Window furniture not surveyed
45	HH;2nd	Replace 2no existing casement sash & make good frame & fanlights (All), new beading to all sections.	Grille	Window furniture not surveyed
46	HH;2nd	Replace existing casement sash & make good frame & fanlight (All), new beading to all sections.	1no pane	Window furniture not surveyed

47	HH;2nd	Replace existing casement sash & make good frame & fanlight (All), new beading to all sections.	None	Window furniture not surveyed
48	HH;2nd	Replace 2no existing casement sash & make good frame & fanlights (All), new beading to all	2no panes	Window furniture not surveyed
49	HH;2nd	Replace existing casement sash & make good frame (All), new beading to all sections.	2no panes	Window furniture not surveyed
50	HH;1st	Replace existing casement sash & make good frame (All), new beading to all sections.	Lead Repair	Window furniture not surveyed
51	HH;1st	Replace 2no existing casement sash & make good frame (All), new beading to all sections.	None	Window furniture not surveyed
52	HH;1st	Replace existing casement sash & make good frame (All), new beading to all sections.	None	Window furniture not surveyed
53	HH;1st	Replace existing casement sash & make good frame (All), new beading to all sections.	Grille	Window furniture not surveyed
54	HH;1st	Replace existing casement sash & make good frame (All), new beading to all sections.	None	Window furniture not surveyed
55	HH;Grnd	Replace existing casement sash & make good frame (All), new beading to all sections.	4no panes	Window furniture not surveyed
56	HH;Grnd	Replace existing casement sash & make good frame (All), new beading to all sections.	None	Window furniture not surveyed
57	HH;Grnd	Replace existing casement sash & make good frame (All), new beading to all sections.	None	Window furniture not surveyed
58	HH;Grnd	Replace existing casement sash & make good frame (All), new beading to all sections.	1no pane	Window furniture not surveyed
59	HH;Grnd	Replace existing casement sash & make good frame (All), new beading to all sections.	None	Window furniture not surveyed
60	HH;Grnd	Replace existing casement sash & make good frame (All), new beading to all sections.	Grille	Window furniture not surveyed
61	HH;Grnd	Replace existing casement sash & make good frame (All), new beading to all sections.	None	Window furniture not surveyed
62	BS;Grnd	Replace existing casement sash & make good frame (All), new beading to all sections.	None	Window furniture not surveyed
63	BS;Grnd	Replace existing casement sash & make good frame (All), new beading to all sections.	None	Window furniture not surveyed
64	BS;Grnd	Replace existing casement sash & make good frame (All), new beading to all sections.	None	Window furniture not surveyed
65	BS;Grnd	Replace existing casement sash & make good frame (All), new beading to all sections.	1no pane	Window furniture not surveyed
66	BS;Grnd	Replace existing casement sash & make good frame (All), new beading to all sections.	1no pane	Window furniture not surveyed
67	BS;Grnd	Replace 2no existing casement sash & make good frame (All), new beading to all sections.	Frosted GW	Window furniture not surveyed
68	BS;Grnd	Replace 2no existing casement sash & make good frame (All), new beading to all sections.	Frosted GW	Window furniture not surveyed
69	BS;Grnd	Replace 2no existing casement sash & make good frame (All), new beading to all sections.	Frosted GW	Window furniture not surveyed
70	BS;1st	Replace existing casement sash & make good frame (All), new beading to all sections.	1no pane	Window furniture not surveyed
71	BS;1st	Replace existing casement sash & make good frame (All), new beading to all sections.	1no pane	Window furniture not surveyed
72	HH;1st	Replace existing casement sash & make good frame (All), new beading to all sections.	TBC	Window furniture not surveyed
73	HH;1st	Replace existing casement sash & make good frame (All), new beading to all sections.	TBC	Window furniture not surveyed
74	HH;1st	Replace existing casement sash & make good frame (All), new beading to all sections.	TBC	Window furniture not surveyed
75	BS;Grnd	Replace existing casement sash & make good frame (All), new beading to all sections.	1no window	Window furniture not surveyed
76	BS;2nd	Replace 2no existing casement sash & make good frame (All), new beading to all sections.	Clear	Window furniture not surveyed
A	HH;Bell	Make good frame (All), repair stone fillet abutting window	1no pane	N/A
B	HH;Bell	Make good frame (All), repair stone fillet abutting window	None	N/A
C	HH;Bell	Make good frame (All) replace bottom section, repair stone fillet abutting window	None	N/A
D	BS;Bell	Make good frame (All) replace bottom section, repair stone fillet abutting window	None	N/A
E	BS;Bell	Make good frame (All), repair stone fillet abutting window	None	N/A

F	BS;Bell	Make good frame & refix loose frame (All), repair stone fillet abutting window	None	N/A