



Image 1: Kingsway
elevation. 40-42 Kingsway
and 36-38 Kingsway
viewed from Kingsway
looking south.

Image2: 61-62 Lincoln's
Inn Fields elevation
viewed from
Lincoln's Inn Fields
looking west



Image 3



Image 4



Image 5

Existing central lightwell in
61-62 Lincoln's Inn Fields.

Image 3: View from rooftop

Image 4: Base of lightwell
at first floor level

Image 5: View looking up
from below.



Image 6: Elevation of
61-62 Lincoln's Inn Fields



Image 7: View from
Lincoln's Inn Fields looking
west towards 61-62
Lincoln's Inn Fields



Image 8: Entry courtyard
at 61-62 Lincoln's Inn
Fields, currently showing
carparking



Image 9: Full street
elevation
(photo merged) of west-
ern terrace of
Lincoln's Inn Fields



Image 10



Image 11



Image 12

Image 10: 36-38 Kingsway
Elevation

Image 11: Upper levels of
36-38 Kingsway showing
turret, gable and
mansard roof.

Image 12: Ground floor
with proposed restaurant
entrance to the right



Image 13



Image 14



Image 15

Image 13: 40-42 Kingsway
elevation by Sir Edwin
Lutyens

Image 14: Existing gable
and chimneys to
40-42 Kingsway building
with detail of junction to
36-38 Kingsway building.

Image 15: Ground floor
retail entrance to
40-42 Kingsway.

PHOTOGRAPHIC RECORD



Image 16: View from
third floor of
40-42 Kingsway looking
up into the lightwell

Image 17: View down
extent of the lighthwell
from the roof level

Image 18: View to
glazed lantern at base
of lightwell on first floor
of 42 Kingsway

PHOTOGRAPHIC RECORD



Image 19



Image 21



Image 23

Image 19: Staircase linking ground and mezzanine of 40-42 Kingsway, Pitcher and Piano



Image 24

Image 20: 40-42 Kingsway third floor

Image 21: Interior of 40-42 Kingsway mezzanine floor overlooking ground, Pitcher and Piano

Image 22: 40-42 Kingsway second floor piano nobile




Image 20




Image 22



Image 25

Image 23: 40-42 Kingsway mezzanine floor looking to the underside of the glazed lantern/lightwell

Image 24: Ceiling detail on the third floor

Image 25: 40-42 Kingsway third floor




Image 26: 40-42
Kingsway piano nobile

Image 27: Balustrade at
top of staircase,
40-42 Kingsway

Image 28: Windows to
rear of 40-42 Kingsway.

Image 29: Balustrade
and stair in 40-42
Kingsway

Image 30: Back room of
piano nobile, second
floor 40-42 Kingsway



Image 31



Image 32



Image 33

Image 31: Louver grill surrounding plantroom above 61-62 Lincoln's Inn Fields (incorporating 36-38 Kingsway)

Image 32: Existing plant, lift overrun and motor room all proposed for demolition

Image 33: Existing top floors of 61-62 Lincoln's Inn Fields (incorporating 36-38 Kingsway) with red brick overclad with roofing slates.