



- 1. Existing yellow stock brick cleaned and repaired
- New wall built with reclaimed yellow stock
- New wall built with red brick

- 7. Timber sash windows reframed to match
- 8. Timber windows with PPC aluminium
- 9. PPC aluminium curtain wall system

- 17. Existing cast Iron column retained
- health and safety reasons and to be rebuilt in modern construction as per original wall
- Rev 00 for more detail)

  24. Top section of façade demolished for health and safetyreasons and to be rebuilt as per original
- (See Application for Conservation Area Consent ProposedPlans PL(D)201 Rev 00 & PL(D)202 Rev 00 for more detail)