

Flat 4, 11 Oval Road, London NW1 7EA



Condition of existing roof. Side elevation of roof hip.

The roof structure has deflected with the weight of the concrete tiles.

There is substantial ingress of water.

The proposal is to replace the concrete tiles with natural slate tiles.