


PURCELL MILLER TRITTON

architects, designers and historic buildings consultants

Round Reading Rooms Drawings Issued

Job No: 230838

Consultant	Drawing Number	Description	Condition no.	notes
TGA	IW560AP-TGA-M-3301	Mechanical Drawing	Condition no.8	
TGA	IW560AP-TGA-M-3302	Mechanical Drawing	Condition no.8	
TGA	IW560AP-TGA-M-7101-A	Mechanical Drawing	Condition no.8	
TGA	IW560AP-TGA-M-7102-A	Mechanical Drawing	Condition no.8	
TGA	IW560AP-TGA-M-7103-A	Mechanical Drawing	Condition no.8	
TGA	IW560AP-TGA-M-7104-A	Mechanical Drawing	Condition no.8	
TGA	IW560AP-TGA-M-7105	Mechanical Drawing	Condition no.8	
TGA	IW560AP-TGA-M-7201-A	Mechanical Drawing	Condition no.8	
TGA	IW560AP-TGA-M-7202-A	Mechanical Drawing	Condition no.8	
TGA	IW560AP-TGA-M-7203-A	Mechanical Drawing	Condition no.8	
TGA	IW560AP-TGA-M-7204-A	Mechanical Drawing	Condition no.8	
TGA	IW560AP-TGA-M-7205	Mechanical Drawing	Condition no.8	
TGA	IW560AP-TGA-M-6101	Mechanical Drawing	Condition no.8	
TGA	IW560AP-TGA-M-6102	Mechanical Drawing	Condition no.8	
TGA	IW560AP-TGA-E-7001	Electrical drawing	Condition no. 8	
TGA	IW560AP-TGA-E-7002	Electrical drawing	Condition no. 8	
TGA	IW560AP-TGA-E-7003	Electrical drawing	Condition no. 8	
TGA	IW560AP-TGA-E-7004	Electrical drawing	Condition no. 8	
TGA	IW560AP-TGA-E-7006-A	Electrical drawing	Condition no. 8	
TGA	IW560AP-TGA-E-7007-A	Electrical drawing	Condition no. 8	
TGA	IW560AP-TGA-E-7008-A	Electrical drawing	Condition no. 8	
TGA	IW560AP-TGA-E-7009-A	Electrical drawing	Condition no. 8	
Atelier One	Design parameters for the Round Reading Room	Report	Condition no.5	
Atelier One	Structural Calculations	Report	Condition no.5	
Atelier One	A1/1578/102 H	Structural drawing	Condition no.5, 9a and b	



Atelier One	A1/1578/103 J	Structural drawing	Condition no.5, 9a and b	
Atelier One	A1/1578/104 E	Structural drawing	Condition no.5, 9a and b	
Atelier One	A1/1578/105 F	Structural drawing	Condition no.5, 9a and b	
Atelier One	A1/1578/106 D	Structural drawing	Condition no.5, 9a and b	
Atelier One	A1/1578/107 A	Structural drawing	Condition no.5, 9a and b	
Atelier One	A1/1578/120 D	Structural drawing	Condition no.5, 9a and b	
Atelier One	A1/1578/121 F	Structural drawing	Condition no.5, 9a and b	
Atelier One	A1/1578/122 E	Structural drawing	Condition no.5, 9a and b	
Atelier One	A1/1578/123 F	Structural drawing	Condition no.5, 9a and b	
Atelier One	A1/1578/124 F	Structural drawing	Condition no.5, 9a and b	
Atelier One	A1/1578/125 C	Structural drawing	Condition no.5, 9a and b	
Atelier One	A1/1578/126 C	Structural drawing	Condition no.5, 9a and b	
Atelier One	A1/1578/127 E	Structural drawing	Condition no.5, 9a and b	
Atelier One	A1/1578/128 G	Structural drawing	Condition no.5, 9a and b	
Atelier One	A1/1578/129 A	Structural drawing	Condition no.5, 9a and b	
Atelier One	A1/1578/130 D	Structural drawing	Condition no.5, 9a and b	
Atelier One	A1/1578/131 A	Structural drawing	Condition no.5, 9a and b	
Atelier One	A1/1578/132 B	Structural drawing	Condition no.5, 9a and b	
Atelier One	A1/1578/133 B	Structural drawing	Condition no.5, 9a and b	
Atelier One	A1/1578/134 B	Structural drawing	Condition no.5, 9a and b	
Atelier One	A1/1578/135 -	Structural drawing	Condition no.5, 9a and b	
Purcell Miller Tritton	230838-09-B	Architectural drawing		information only
Purcell Miller Tritton	230838-010	Architectural drawing	Condition no.9, c	
Purcell Miller Tritton	230838-011-C	Architectural drawing	Condition no.9, c	
Purcell Miller Tritton	230838-012-D	Architectural drawing	Condition no.9, d	
Purcell Miller Tritton	230838-015-E	Architectural drawing	Condition no.9, d	
Purcell Miller Tritton	230838-016-B	Architectural drawing		information only
Purcell Miller Tritton	230838-017-D	Architectural drawing		coordination drawing
Purcell Miller Tritton	230838-025	Architectural drawing	Condition no. 9, d	
Purcell Miller Tritton	230838-026-B	Architectural drawing	Condition no. 9, d	
Purcell Miller Tritton	230838-027-D	Architectural drawing	Condition no.9, d	
Purcell Miller Tritton	230838-028-B	Architectural drawing	Condition no.9, d	
Purcell Miller Tritton	230838-030-D	Architectural drawing	Condition no.9, d	
Purcell Miller Tritton	230838-031-A	Architectural drawing	Condition no.9, d	

22 MAR 2007

Coniston	Coniston	Method Statemet	Condition no.9, e	Protection to delivery route
----------	----------	-----------------	-------------------	------------------------------

RECEIVED
22 MAR 2007